



**CABRERA SERVICES**  
RADIOLOGICAL ENVIRONMENTAL REMEDIATION

Br. 3

August 28, 2015

Regional Administrator  
U.S. Nuclear Regulatory Commission, Region I  
2100 Renaissance Boulevard, Suite 100  
King of Prussia, PA 19406  
ATTN: Director, Division of Nuclear Materials Safety

03035316

RE: NRC Radioactive Materials License No. 06-30556-01, Amendment No. 08  
Completion of Job Activities at Temporary Job Site  
WR110, Building 214, Room 201 at the Hill Air Force Base, Utah (Control No. 587122)

REC RG 1 0831 15PM 1018

Cabrera Services Inc. (Cabrera) is providing this written notification of completion of job activities at the WR110, Building 214 temporary job site. The following information is provided in accordance with License Condition No. 18B:

1. **Temporary job site status:** Cabrera has complete its current phase of characterization in Room 201 and has returned radiological control to the U.S. Air Force Radioisotope Committee (AFRIC).
2. **Disposition of any licensed radioactive material:**
  - Cabrera took possession of no licensed radioactive material during the course of field work.
  - Three (3) exempt quantity radioactive check sources were used to perform routine response checks and efficiency determinations of field radiological survey instruments and; were removed from site at the completion of field work.
  - Radiological surveys were conducted by Cabrera during/after completion of work activities to confirm the absence of residual surface radioactivity on tools & equipment used during field work; all final survey results were below clearance/screening levels established for Cabrera's licensed Radiation Safety Program.

If you should have any questions regarding this notice, please contact me at (352) 610-2150.

Sincerely,

Michael S. Winters, CHP  
Radiation Safety Officer

588872  
NMSS/RGN1 MATERIALS-002

This is to acknowledge the receipt of your letter application dated

August 28, 2015, and to inform you that the initial processing which includes an administrative review has been performed.

Notification (06-30556-01) There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

---

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 588872.

When calling to inquire about this action, please refer to this control number.

You may call us on (610) 337-5398, or 337-5260.