

## Saxton, John

---

**From:** Mike Gaither <mike.gaither@UR-Energy.com>  
**Sent:** Monday, October 19, 2015 5:18 PM  
**To:** Brian Wood; Saxton, John  
**Cc:** Kurt Brown; Jay Douthit; John Cash; Steven Hatten; Chris Pedersen; Gersey, Linda  
**Subject:** [External\_Sender] Lost Creek Release Report: HH1-11 Trunk

An unplanned release reportable to WDEQ-WQD occurred at the Lost Creek ISR Project site (PT788) that was reported via the WQD spill report webpage (Incident ID 151019-1447). The release was reportable due to the fluid reaching a dry, ephemeral drainage. The estimated volume of the release was 139 gallons based on the area of impact.

A release of production fluid near Header House 1-11 (HH1-11) was initially found by a Wellfield Operator on Saturday October 17, 2015 at approximately 11:00 which was reported to the Mine Manager. The release was estimated at approximately 60 gallons and covered a small area. The release did not impact drainage and was not reportable at the time. The cause was unknown and the operation of HH1-11 was shut down for troubleshooting. Production flows from wells were reconfigured on Sunday October 18 and the Header House turned back on. The leak then continued and at approximately 1700 hrs the flow reached the dry ephemeral drainage and HH1-11 operation was again halted.

The spill was located approximately 100 feet west of HH1-11 at T25N R92W Section 20 NWNW qtr-qtr.

If you have any questions please feel free to contact me.

Regards,

**Michael Gaither**  
Manager EHS and Regulatory Affairs  
Ur-Energy USA Inc.  
5880 Enterprise Dr. Suite 200  
Casper, WY 82609 USA  
(307) 265-2373 ext. 321

