

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Ashok K. Gupta, MD.
610 East Twelve Mile Rd
Madison Heights, MI 48071

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

REPORT NUMBER(S) 15-01

3. DOCKET NUMBER(S)

030-36604

4. LICENSE NUMBER(S)

21-32524-01

5. DATE(S) OF INSPECTION

10/29/15

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	E.L. Kulzer	<i>E.L. Kulzer</i>	10/29/15
BRANCH CHIEF		<i>[Signature]</i>	11/6/15

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Ashok K. Gupta, M.D. 610 East Twelve Mile Rd Madison Heights, MI 48071 REPORT NUMBER(S) 2015001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-36604	4. LICENSE NUMBER(S) 21-32524-01	5. DATE(S) OF INSPECTION 10/29/2015
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED IP 87130	7. INSPECTION FOCUS AREAS 03.01 through 03.07
---	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT A. Gupta, M.D., RSO	4. TELEPHONE NUMBER (248) 589-9111
---------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: 10/29/2020

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was a routine unannounced inspection of a private practice cardiology clinic authorized to use licensed material permitted by 10 CFR Section 35.200. Nuclear cardiology studies were only performed on Thursdays. The clinic employed one part-time technologist who performs 3-8 patient studies each week. The licensee obtained only unit doses from a local radiopharmacy.

This inspection consisted of interviews with licensee personnel, a review of selected records, a tour of the nuclear medicine department, and independent measurements. The inspection included observations of dose calibrator QA checks, security of licensed material, use of personnel monitoring, package receipt, and surveys. The inspector observed the licensee personnel prepare and administer unit doses for cardiac rest and stress testing procedures.

The inspector determined that all licensed material was secured and accounted for which included all sealed and check sources. These were secured by securing the hot lab door. The failure to secure the hot lab door was a violation during the last inspection which is now considered closed.

No violations of NRC regulatory requirements were identified during this inspection.