

### SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

HHC Health Care, LLC  
450 North New Ballas Road  
Suite 270 West Wing  
St. Louis, MO 63141

REPORT NUMBER(S) 15-001

2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-38828

4. LICENSE NUMBER(S)

24-35232-01

5. DATE(S) OF INSPECTION

October 20, 2015

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

\_\_\_\_\_ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
(Violations and Corrective Actions)

#### Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Deborah A. Piskura/Navid Tehrani		10/20/15
BRANCH CHIEF	Aaron McCraw		11/9/15

**Docket File Information**

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  HHC Health Care, LLC 450 North New Ballas Road Suite 270 West Wing St. Louis, MO 63141  REPORT NUMBER(S) 15-001	2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S)  030-38828	4. LICENSE NUMBER(S)  24-35232-01	5. DATE(S) OF INSPECTION  October 20, 2015
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED  87130	7. INSPECTION FOCUS AREAS  03.01 -03.08
--	---

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S)  02201	2. PRIORITY  5	3. LICENSEE CONTACT  Allen Soffer, M.D., RSO	4. TELEPHONE NUMBER  (314) 991-6969
---------------------------------	----------------------	--	---

Main Office Inspection                      Next Inspection Date: 10/20/2020

Field Office Inspection \_\_\_\_\_

Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

This was an initial inspection of a diagnostic clinic (opened M-F) authorized for materials in Sections 35.100 and 35.200. The licensee performed approximately 55 diagnostic cardiology procedures per month (technetium-99m). The licensee initiated licensed activities on June 1, 2015. Three full-time nuclear medicine technologists performed all patient procedures daily. The licensee obtained unit doses of licensed material from an area nuclear pharmacy. The licensee does not possess a dose calibrator. The licensee relies on the pharmacy's assay. A contract physicist performed biannual program of audits the radiation safety program.

**Performance Observations**

The inspectors reviewed select records, interviewed select staff, and performed independent surveys. The inspectors observed the licensee staff administer one diagnostic dosage of technetium-99m. The inspectors observed that the licensee personnel wore their assigned dosimetry. The licensee staff demonstrated package receipt, daily surveys, and waste handling and disposal procedures. The inspectors determined that licensed material was adequately secured.

No violations of NRC requirements were identified during this inspection.