

NRC INSPECTION MANUAL

DIRS

Change Notice 15-031

DELETED:

TRANSMITTED:

<u>Number</u>	<u>Date</u>	<u>Number</u>	<u>Date</u>
1. IMC 2515 App B	08/18/11	IMC 2515 App B	12/18/15
2. IP 95003	02/09/11	IP 95003	12/18/15

TRAINING: No

REMARKS: IMC 2515 Appendix B, "Supplemental Inspection Program," has been revised to partially address RO FBF 95003-1976. The FBF will be closed upon subsequent revisions to IP 95002 and IP 95003 to reference Attachment 2. Terminology enhancements and clarifications associated with "should vs. shall" and "governance vs. requirement vs. guidance" were incorporated. Grammatical, typographical, formatting, and code transfer issues were also corrected.

IP 95003, "Supplemental Inspection for Repetitive Degraded Cornerstones, Multiple Degraded Cornerstones, Multiple Yellow Inputs or One Red Input," has been revised address ROP FBF 95003-1960 (replaced "safety culture components" with "safety culture traits"). Partially addressed ROP Independent Assessment Recommendation 1, ROP FBFs 95003-1967, 95003-1976, and 95003-1991

DISTRIBUTION:

Standard

Official Use Only (OUO)-Security Related Information.

Please contact: _____ Phone: _____

END