

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

MikRon, Inc.
16 Pond Edge Trail
Wareham, Massachusetts 02571
Location: Blood Bank of Alaska, 4000 Laurel St., Anchorage, AK
REPORT NO: 050-00020/2015-001

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission - Region IV
1600 East Lamar Boulevard
Arlington, Texas 76011-4511

3. DOCKET NUMBER
150-00020

4. LICENSE NUMBER
56-0673 (Massachusetts)

5. DATE OF INSPECTION
September 14 through 21, 2015

LICENSEE:



The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	R. Rick Muñoz		09/21/2015
BRANCH CHIEF	G. Michael Vasquez Brooke G. Smith		11/11/15

Munoz, Rick

From: Munoz, Rick
Sent: Monday, September 21, 2015 3:48 PM
To: jim@mikroninc.com
Cc: Munoz, Rick
Subject: NRC Inspection Documentation
Attachments: MIKRON INC - RECIPROACITY 2015.pdf

Jim,

As per our discussion via telephone this morning pertaining to authorization filed under NRC form 241 for reciprocity, I have attached the NRC inspection report documenting your activities conducted under your Massachusetts nuclear material license #56-0673 at the Blood Bank of Alaska located at 4000 Laurel Street in Anchorage, Alaska on September 15, 2015. If you have any questions, please feel free to contact me.

Regards,

Rick Muñoz
Nuclear Materials Inspector
U.S. Nuclear Regulatory Commission, Region-IV
1600 East Lamar Boulevard
Arlington, Texas 76011-4511

Office: (817) 200-1220
Cell: (512) 773-8520
Fax: (817) 200-1188
Email: rick.munoz@nrc.gov



The information contained in this message may be privileged and/or confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please notify the sender immediately by replying to the message and deleting the material from any computer.

Note: Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of the Nuclear Regulatory Commission, Region-IV or the Nuclear Materials Safety Branch-A. All e-mails are subject to monitoring and archival.

Finally, the recipient should check this message and any attachments for the presence of viruses. The Nuclear Regulatory Commission accepts no liability for any damage caused by any virus transmitted by this e-mail.
