

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)**

CONTROL NO: 7927

FILE: INCIDENT REPORT FILE

|   |                 |                        |                       |                   |                        |     |                          |
|---|-----------------|------------------------|-----------------------|-------------------|------------------------|-----|--------------------------|
| FROM: Duke Power Company<br>Charlotte, N.C. 28242<br>Wm. O. Parker, Jr. |                 | DATE OF DOC<br>7-18-75 | DATE REC'D<br>7-25-75 | LTR<br>XX         | TWX                    | RPT | OTHER                    |
| TO: Mr. Norman C. Moseley   |                 | ORIG<br>1 signed       | CC                    | OTHER             | SENT AEC PDR <u>XX</u> |     | SENT LOCAL PDR <u>XX</u> |
| CLASS   | UNCLASS<br>XXXX | PROP INFO              | INPUT                 | NO CYS REC'D<br>1 | DOCKET NO:<br>50-269   |     |                          |

DESCRIPTION: Ltr trans the following:

ENCLOSURES: Abnormal Occurrence A0-50-269/  
75-8 on 7-4-75 re failure to provide required emergency power sources....

(1 Orig yc encl rec'd) **Do Not Remove**

**ACKNOWLEDGED**

PLANT NAME: Oconee Unit 1

FOR ACTION/INFORMATION **DHL 7-29-75**

|                         |                            |                             |                        |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (L)<br>W/ Copies | SCHWENCER (L)<br>W/ Copies | ZIEMANN (L)<br>W/ Copies    | REGAN (E)<br>W/ Copies |
| CLARK (L)<br>W/ Copies  | STOLZ (L)<br>W/ Copies     | DICKER (E)<br>W/ Copies     | LEAR (L)<br>W/ Copies  |
| PARR (L)<br>W/ Copies   | VASSALLO (L)<br>W/ Copies  | KNIGHTON (E)<br>W/ Copies   | SPELS<br>W/ Copies     |
| KNIEL (L)<br>W/ Copies  | ✓ PURPLE (L)<br>W/3 Copies | YOUNGBLOOD (E)<br>W/ Copies | W/ Copies              |

**INTERNAL DISTRIBUTION**

|                                |                          |                    |                          |                      |
|--------------------------------|--------------------------|--------------------|--------------------------|----------------------|
| <del>REG FILE</del><br>NRC PDR | TECH REVIEW<br>SCHROEDER | DENTON<br>**GRIMES | LIC ASST<br>R. DIGGS (L) | A/T IND.<br>BRAITMAN |
| OGC, ROOM P-506A               | MACCARY                  | GAMMILL            | H. GEARIN (L)            | SALTZMAN             |
| GOSSICK/STAFF                  | KNIGHT                   | KASTNER            | E. GOULBOURNE (L)        | MELTZ                |
| CASE                           | PAWLICKI                 | BALLARD            | P. KREUTZER (E)          |                      |
| GIAMBUSSO                      | SHAO                     | SPANGLER           | J. LEE (L)               | PLANS                |
| BOYD                           | **STELLO                 |                    | M. RUSHEROOK (L)         | MCDONALD             |
| MOORE (L)                      | **HOUSTON                | ENVIRO             | S. REED (E)              | CHAPMAN              |
| DEYOUNG (L)                    | **NOVAK                  | MULLER             | M. SERVICE (L)           | DUBE (Ltr)           |
| SKOVHOLT (L)                   | ROSS                     | DICKER             | ✓ S. SHEPPARD (L)        | E. COUPE             |
| GOLLER (L) (Ltr)               | IPPOLITO                 | KNIGHTON           | M. SLATER (E)            | PETERSON             |
| P. COLLINS                     | TEDESCO                  | YOUNGBLOOD         | H. SMITH (L)             | HARTFIELD (2)        |
| DENISE                         | J. COLLINS               | REGAN              | S. TEETS (L)             | KLECKER              |
| REG OPR                        | LAINAS                   | PROJECT LDR        | G. WILLIAMS (E)          | EISENHUT             |
| FILE & REGION (2)              | BENAROYA                 |                    | V. WILSON (L)            | *WIGGINTON           |
| MIPC/PE (3)                    | VOLLMER                  | HARLESS            | R. INGRAM (L)            | F. WILLIAMS          |
| STEELE                         |                          |                    | M. DUNCAN (E)            | HANAUER              |

**EXTERNAL DISTRIBUTION**

|   |                                |   |
|---|--------------------------------|---|
| 1 - LOCAL PDR <u>Walhalla, S.C.</u>               | 1 - NATIONAL LABS              | 1 - PDR-SAN/LA/NY                       |
| 1 - TIC (ABERNATHY) (1)(2)(10)                    | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB                  |
| 1 - NSIC (BUCHANAN)                               | 1 - CONSULTANTS                | 1 - G. ULRIKSON, ORNL                   |
| 1 - ASLB  | NEWMARK/BLUME/AGBABIAN         | 1 - AGMED (RUTH GUSSMAN)<br>Rm B-127 GT |
| 1 - Newton Anderson                               |                                | 1 - J. D. RUNKLES, Rm E-201<br>GT       |
| 5 - ACRS SENT TO LIC ASST <b>Sheppard 7-29-75</b> |                                |   |
| ** SEND ONLY TEN DAY REPORTS                      |                                |   |

*A104 W*

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

TELEPHONE: AREA 704  
373-4083

July 18, 1975

Regulatory Docket File

Mr. Norman C. Moseley, Director  
U. S. Nuclear Regulatory Commission  
Suite 818  
230 Peachtree Street, Northwest  
Atlanta, Georgia 30303

Re: Oconee Unit 1  
Docket No. 50-269

Dear Mr. Moseley:


Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station  
Technical Specifications, please find attached Abnormal Occurrence  
Report A0-269/75-8.

Very truly yours,

*William O. Parker, Jr.*  
William O. Parker, Jr.

MST:vr  
Attachment

cc: Mr. Angelo Giambusso



7927

DUKE POWER COMPANY  
OCONEE UNIT 1

Report No.: AO-269/75-8

Approved 17/117 Rptd **7-18-75**

Report Date: July 18, 1975

Date of Occurrence: July 4, 1975

Facility: Oconee Unit 1, Seneca, South Carolina

Identification of Occurrence: Failure to provide required emergency power sources

Conditions Prior to Occurrence: Units 1 and 3 at 100 percent full power;  
Unit 2 shut down

Description of Occurrence:

On July 3, 1975 at 1835, it was determined that Keowee Hydro Station, Unit 2, could not be synchronized to the system and thus was declared inoperable. In accordance with Technical Specification 3.7.2(b), continued power operation is permitted for up to 24 hours provided the operable Keowee unit is connected to the operable underground feeder circuitry. It was expected that maintenance of the unit would not exceed the allowable 24 hour maintenance period.

At approximately 1600 on July 4, 1975, it was determined that Keowee Unit 2 would possibly not be operable by 1835, the end of the allowable maintenance period. The provisions of Technical Specification 3.7.4 allow continued power operation, but require that the 4160 volt standby buses be energized within 30 minutes by one of the Lee combustion turbines through the isolated 100 kV transmission line.

Due to highly active thunderstorms in the area, and heavy usage of the two transmission lines between the Lee Steam Station and the Central switchyard, the system dispatcher decided to wait until 1800 to place a combustion turbine in service. At 1800, the Lee Steam Station operator was notified that backup emergency power was required for Oconee. An attempt to place a combustion turbine in service on a non-isolated 100 kV transmission line resulted in the combustion turbine tripping at 1820. A shutdown of operating reactors was initiated at 1835 and continued until 1903 when transformer CT-5 was energized by a Lee combustion turbine on the isolated transmission line. Keowee Unit 2 was declared operational at 2316 July 4, 1975.

Designation of Apparent Cause of Occurrence:

Keowee Unit 2 was declared inoperable due to its inability to automatically start and synchronize with the system grid. This was traced to a misadjusted governor on the unit.

The Lee combustion turbine was not initially put on the isolated transmission system based upon the dispatcher's assessment of the most reliable system configuration during the thunderstorm. This was not in accordance with established procedures and resulted in the combustion turbine tripping.

Analysis of Occurrence:

The Keowee Hydro Station provides two redundant sources of emergency power for Oconee. The Lee combustion turbine, through the isolated 100 kV transmission line, is a source of backup emergency power in the event there is a loss of normal and startup transformers for all three units, a loss of both Keowee units and a system-wide blackout. In this incident, only one Keowee hydro unit was inoperable for approximately five hours longer than permitted by Technical Specifications. The operating Keowee hydro unit did not have a backup emergency power source for approximately ½ hour longer than permitted by Technical Specifications. Throughout this incident, all buses remained energized with several redundant sources of power available from the operating Oconee units and the 230 and 500 kV system grids. It is concluded that the health and safety of the public was not affected by this incident.

Corrective Action:

Keowee Unit 2 was returned to service and tested satisfactorily. The Lee combustion turbine was placed in service on the isolated 100 kV transmission line and performed satisfactorily. In order to prevent a future recurrence, system dispatching personnel will be reminded of the unique requirements of a nuclear station with regard to emergency power sources.