

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 8915

FILE: INCIDENT REPORT FILE

FROM: Duke Power Company Charlotte, NC W O Parker Jr		DATE OF DOC 8-15-75	DATE REC'D 8-21-75	LTR XX	TWX	RPT	OTHER
TO: Mr Moseley		ORIG one signed	CC	OTHER	SENT AEC PDR <u>XX</u>		SENT LOCAL PDR <u>XX</u>
CLASS	UNCLASS XXXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-269		

DESCRIPTION:
Ltr trans the following:

PLANT NAME: Oconee #1

ENCLOSURES:
Unusual Event Report #75-7 on 7-3-75 concerning modification completion without prior authorization with regard to turbine generators.....

DO NOT REMOVE
ACKNOWLEDGED

FOR ACTION/INFORMATION 8-25-75 ehf

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/3Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	--	--	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR <u>Walhalla, S.C.</u>	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
1 - ACRS SENT TO LIC ASST <u>Sheppard</u>		
** SEND ONLY TEN DAY REPORTS		

DUKE POWER COMPANY

POWER BUILDING


422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

REGULATORY DOCKET FILE COPY

TELEPHONE: AREA 704
373-4083

August 15, 1975




Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Re: Oconee Unit 1
Docket No. 50-269

Dear Mr. Moseley:


Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station
Technical Specifications, please find attached Unusual Event Report
UE-269/75-7.

Very truly yours,


William O. Parker, Jr.

MST:vr
Attachment

cc: Mr. Angelo Giambusso



8915

AUG 18 11 32 AM '74

REGISTRATION
SECTION

DUKE POWER COMPANY
OCONEE UNIT 1

Report No.: UE-269/75-7

Report Date: August 15, 1975

Event Date: July 3, 1975

Facility: Oconee Unit 1, Seneca, South Carolina

Identification of Event: Modification completed without prior authorization

Conditions Prior to Event: Not applicable

Description of Event:

On August 22, 1974, a request for a station modification to the Oconee turbine generators and Keowee hydro generators was initiated by Duke personnel external to the station organization. The modification to the loss-of-field-excitation relay KLF-1 was determined to be necessary because voltage elements in the relay were incorrectly rated for their application. The modification was classified as safety-related and was processed by the appropriate personnel in the prescribed fashion. The complete modification package, including the procedure for implementation, safety evaluation, and quality assurance documentation, was forwarded to the station for the appropriate Station Review Committee review and approval and station manager approval required prior to implementation. The modification was implemented, however, prior to receiving SRC and station manager approval. The turbine generator modifications were completed in December, 1974 and the Keowee modifications in February, 1975. This incident was discovered on July 3, 1975 during a review of records.

Designation of Apparent Cause of Event:

The apparent cause of this event was a misunderstanding of the approvals required prior to implementation of modifications at a nuclear station by the personnel involved. These personnel were not assigned to the station organization.

Analysis of Event:

The KLF-1 relay serves to protect the Oconee turbine generators and the Keowee hydro generators in the event of a loss-of-field-excitation. Prior to the modification, it was believed that several spurious trips of the turbine generator had been experienced due to the improper rating of the voltage elements. This modification has increased the reliability of all generating units. It is concluded that the health and safety of the public was not affected by this incident.

Corrective Action:

Subsequent to implementation, this modification has been reviewed and approved. The Administrative Policy Manual for Nuclear Stations was revised December 20, 1974 to more clearly define the reviews and approvals required prior to implementation of station modifications to prevent a similar recurrence. In addition, the requirement to have required approvals prior to implementing a station modification has been re-emphasized to the organization involved.

50

AUG 10 11 13 AM '75

U.S. AIR FORCE
REGISTRATION DIVISION
MEMPHIS, TN