



VERMONT YANKEE NUCLEAR POWER CORPORATION

SEVENTY SEVEN GROVE STREET

RUTLAND, VERMONT 05701

REPLY TO:

ENGINEERING OFFICE

TURNPIKE ROAD

WESTBORO, MASSACHUSETTS 01581

TELEPHONE 617-366-9011

September 19, 1978

United States Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Office of Nuclear Reactor Regulation
Division of Operating Reactors

References: (a) License No. DPR-28 (Docket No. 50-271)
(b) USNRC Letter to VYNPC Dated August 29, 1978

Dear Sir:

Subject: Control Rods Failing to Fully Insert on Scram

Your letter, Reference (b), requested that we review our 1977 scram records to identify any instances when control rods failed to fully insert, upon a scram. In response to this request VYNPC has reviewed the records and concludes that no such events have occurred at Vermont Yankee.

We trust this information is satisfactory; however, should you desire additional information, please feel free to contact us.

Very truly yours,

VERMONT YANKEE NUCLEAR POWER CORP.

Robert H. Groce
Licensing Engineer

RHG/em

WVY 78087

RECEIVED
DIST. DIVISION
ARCH. SERVICES

1978 SEP 22 AM 10 44

RECEIVED DISTRIBUTION
SERVICES UNIT

780880345

1001
5/10