

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

| | | | |
|--|-------------------------------------|--|--|
| 1. LICENSEE/LOCATION INSPECTED: Medical Faculty Associates Heart Care Imaging, Inc. 2150 Pennsylvania Avenue, NW, Suite 4-405 Washington, DC 20037 REPORT NUMBER(S) 2016001 | | 2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713 | |
| 3. DOCKET NUMBER(S) 03037218 | 4. LICENSE NUMBER(S) 08-31160-01 | 5. DATE(S) OF INSPECTION February 2 and 3, 2016; In office review February 16, and February 17 | |

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.




Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):

4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

SEE NEXT PAGE

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

| Title | Printed Name | Signature | Date |
|---------------------------|----------------|--|---------|
| LICENSEE'S REPRESENTATIVE | James Avery |  | 2-25-16 |
| NRC INSPECTOR | Farrah Gaskins |  | 2/25/16 |
| BRANCH CHIEF | James P. Dwyer |  | 2/25/16 |

SUNSI Review Completed By: / RA / FGaskins Public Non-Sensitive

This document becomes an NRC Official Agency Record once it is signed by the Branch Chief

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

| | | | |
|--|---|---|--|
| 1. LICENSEE/LOCATION INSPECTED; Medical Faculty Associates Heart Care Imaging, Inc. 2150 Pennsylvania Avenue, NW, Suite 4-405 Washington, DC 20037 REPORT NUMBER(S) 2016-001 | | 2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713 | |
| 3. DOCKET NUMBER(S) 03037218 | 4. LICENSE NUMBER(S) 08-31160-01 | 5. DATE(S) OF INSPECTION February 2 and 3, 2016; In office review February 16, and February 17 | |

(Continued)

- A. Regulations set forth in 30.34(b) requires in part that no license issued or granted nor any right under a license shall be transferred through transfer of control of any license to any person, unless the commission shall, after securing full information, find that the transfer is in accordance with the provisions of the Act and shall give its consent in writing.

Contrary to the above, on March 28, 2014 the licensee transferred control of their location at 2150 Pennsylvania Avenue, Room D-227 for unrestricted use. Specifically, the licensee moved all of the equipment from the location and began to remodel the facility. The licensee submitted close-out surveys on April 2, which were performed on April 1.

- B. Regulations set forth in 35.13 (f) require in part that a licensee shall apply and must receive a license amendment before it changes the address of use identified on the license.

Contrary to the above, the licensee did not receive an amendment before changing an address of use on the license. Specifically on April 1, 2014, the licensee began using licensed material at 2300 M Street NW, 8th Floor, a location not approved on the license. The licensee did not receive approval to use material at that location until June 12, 2014.

This is a Severity Level IV Violation (Section 6.3)