

Entergy Nuclear Operations, Inc. (Indian Point Units 2 and 3),  
 Docket Nos. 50-247-LR and 50-286-LR, ASLBP No. 07-858-03-LR-BD01

Evidentiary Hearing

**Entergy (“ENT”) TRACK 2 Hearing Exhibits**

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENTR16001                | All   | Entergy Hearing Exhibit List (“ENT Exhibit List”)                                 | 10/29/2015                     | [Revised]                               |
| ENT00015A-B              | All   | Indian Point Energy Center License Renewal Application (April 2007)               | 3/28/2012                      | X                                       |
| ENTR00031                | NYS-26B/RK-TC-1B, NYS-38/RK-TC-5, NYS-25        | <i>Curriculum Vitae</i> of Alan B. Cox  | 8/10/2015                      | [Revised]                               |
| ENT000032                | NYS-26B/RK-TC-1B, NYS-38/RK-TC-5, NYS-25        | <i>Curriculum Vitae</i> of Nelson F. Azevedo                                      | 3/28/2012                      | X                                       |
| ENT000041                | NYS-38/RK-TC-5                                  | NRC, Audit Report for Plant Aging Management Programs and Reviews (Jan. 13, 2009) | 3/28/2012                      | X                                       |

| Entergy Exhibit # | Track 2 Contentions Addressed by Exhibit | Exhibit Name  | Exhibit Submission Date | Admitted During Track 1 Hearing? |
|-------------------|--|---|-------------------------|----------------------------------|
| ENT000089         | NYS-26B/RK-TC-1B                         | Declaration of Dr. Joram Hopenfeld in Support of New England Coalition's Motion for Reconsideration (Dec. 15, 2008)   | 3/28/2012               | X                                |
| ENT000098         | NYS-25                                   | NEI 95-10, Industry Guideline for Implementing the Requirements of 10 CFR Part 54 – The License Renewal Rule, Rev. 6 (June 2005)  | 3/28/2012               | X                                |
| ENT000182         | NYS-26B/RK-TC-1B                         | Entergy Statement of Position Regarding Contention NYS-26/RK-TC-1B (Metal Fatigue)  | 3/29/2012               | X                                |
| ENT000183         | NYS-26B/RK-TC-1B                         | Testimony of Entergy Witnesses Nelson F. Azevedo, Alan B. Cox, Jack R. Strosnider, Robert E. Nickell, and Mark A. Gray Regarding Contention NYS-26/RK-TC-1B (Metal Fatigue) | 3/29/2012               | X                                |
| ENTR00184         | NYS-26B/RK-TC-1B, NYS-38/RK-TC-5, NYS-25 | <i>Curriculum Vitae</i> of Jack R. Strosnider   | 8/10/2015               | [Revised]                        |
| ENTR00185         | NYS-26B/RK-TC-1B, NYS-38/RK-TC-5         | <i>Curriculum Vitae</i> of Robert E. Nickell  | 8/20/2012               | [Revised]                        |
| ENTR00186         | NYS-26B/RK-TC-1B, NYS-38/RK-TC-5, NYS-25 | <i>Curriculum Vitae</i> of Mark A. Gray   | 8/10/2015               | [Revised]                        |
| ENT000187         | NYS-26B/RK-TC-1B                         | ASTM Vol. 03.01, Metals – Mechanical Testing; Elevated and Low Temperature Tests; Metallography (2005) (excerpted)  | 3/29/2012               | X                                |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENT000188                | NYS-26B/RK-TC-1B                                | ASME, Criteria of the ASME Boiler and Pressure Vessel Code for Design by Analysis in Sections III and VIII, Division 2 (1969)   | 3/29/2012                      | X                                       |
| ENT000189                | NYS-26B/RK-TC-1B                                | SAND94-0187, Evaluation of Conservatism and Environmental Effects in ASME Code, Section III, Class 1 Fatigue Analysis (Aug. 1994)   | 3/29/2012                      | X                                       |
| ENT000190                | NYS-26B/RK-TC-1B, NYS-38/RK-TC-5                | Memorandum from Ashok C. Thadani to William D. Travers, Closeout of Generic Safety Issue 190, Fatigue Evaluation of Metal Components for 60-year Plant Life (Dec. 26, 1999)                         | 3/29/2012                      | X                                       |
| ENT000191                | NYS-26B/RK-TC-1B                                | K. R. Rao, Companion Guide to the ASME Boiler & Pressure Vessel Code (3rd ed. 2009) (excerpted)   | 3/29/2012                      | X                                       |
| ENT000192                | NYS-26B/RK-TC-1B, NYS-38/RK-TC-5, NYS-25        | NRC Regulatory Issue Summary 2011-05, Information on Revision 2 to the Generic Aging Lessons Learned Report for License Renewal of Nuclear Power Plants (July 1, 2011)                              | 3/29/2012                      | X                                       |
| ENT000193                | NYS-26B/RK-TC-1B, NYS-25                        | NL-08-092, Letter from Fred R. Dacimo, Entergy, to NRC, Amendment 5 to License Renewal Application (June 11, 2008)  | 3/29/2012                      | X                                       |
| ENT000194                | NYS-26B/RK-TC-1B                                | NL-08-084, Letter from Fred R. Dacimo, Entergy, to NRC, Reply to Request for Additional Information Regarding License Renewal Application – Time-Limited Aging Analyses and Boraflex (May 16, 2008) | 3/29/2012                      | X                                       |
| ENTR00195                | NYS-26B/RK-TC-1B                                | NUREG-2101, Safety Evaluation Report Related to the License Renewal of Salem Nuclear Generating Station § 4.3 (Jun. 2011) (except)  | 8/10/2015                      | [Revised]                               |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENT000196                | NYS-26B/RK-TC-1B, NYS-38/RK-TC-5                | Westinghouse Level 2 Policy/Procedure NSNP 3.2.6, Design Analysis (Mar. 2011) [PROPRIETARY]   | 3/29/2012                      | X                                       |
| ENT000197                | NYS-26B/RK-TC-1B, NYS-38/RK-TC-5                | Letter from P. Davison, PSEG Nuclear, LLC, to NRC, Close-out of the NRC Audit Associated with Use of WESTEMS™ Related to the Salem Nuclear Generating Station, Units 1 and 2 License Renewal Application (Feb. 24, 2011)  | 3/29/2012                      | X                                       |
| ENT000198                | NYS-26B/RK-TC-1B                                | Letter from Paul Bessette, Entergy, to Janice Dean, NYS, Twenty-Second Update to Disclosures Pursuant to 10 C.F.R. § 2.336; Entergy Nuclear Operations, Inc. (Indian Point Nuclear Generating Units 2 and 3), Docket Nos. 50-247- LR and 50-286-LR (Dec. 1, 2010) | 3/29/2012                      | X                                       |
| ENT000199                | NYS-26B/RK-TC-1B                                | Westinghouse Calculation Note Number CN-PAFM-09-100, Rev. 0, Indian Point Unit 2 Insurge/Outsurge and Environmental Fatigue Evaluations, (Jun. 10, 2010) [PROPRIETARY]  | 3/29/2012                      | X                                       |
| ENT000200                | NYS-26B/RK-TC-1B                                | Westinghouse Calculation Note Number CN-PAFM-09-63, Rev. 0, Indian Point Unit 2 Pressurizer Insurge/Outsurge Transient Development (June 18, 2010) “) [PROPRIETARY]   | 3/29/2012                      | X                                       |
| ENT000201                | NYS-26B/RK-TC-1B                                | Westinghouse Calculation Note Number CN-PAFM-08-109, Rev. 0, Indian Point Units 2 and 3 Transfer Function Database Development for Hot Leg Surge Nozzle (June 18, 2010) [PROPRIETARY]   | 3/29/2012                      | X                                       |
| ENT000202                | NYS-26B/RK-TC-1B                                | Westinghouse Calculation Note Number CN-PAFM-08-78, Rev. 0, Indian Point Unit 2 and Unit 3: Transfer Function Database Development for Hot Leg Charging Nozzle (June 18, 2010) [PROPRIETARY]  | 3/29/2012                      | X                                       |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENT000203                | NYS-26B/RK-TC-1B                                | Westinghouse Calculation Note Number CN-PAFM-08-116, Rev. 0, Indian Point Unit 2 BIT Nozzle Transfer Function Database Development (June 18, 2010) [PROPRIETARY]                            | 3/29/2012                      | X                                       |
| ENT000204                | NYS-26B/RK-TC-1B                                | Westinghouse Calculation Note Number CN-PAFM-08-103, Rev. 0, Indian Point Units 2 and 3 Transfer Function Database Development for Accumulator Nozzles (June 17, 2010) [PROPRIETARY]        | 3/29/2012                      | X                                       |
| ENT000205                | NYS-26B/RK-TC-1B                                | Westinghouse Calculation Note Number CN-PAFM-09-105, Rev. 0, Indian Point Unit 3 Insurge/Outsurge and Environmental Fatigue Evaluations (June 22, 2010) [PROPRIETARY]                       | 3/29/2012                      | X                                       |
| ENT000206                | NYS-26B/RK-TC-1B                                | Westinghouse Calculation Note Number CN-PAFM-09-74, Rev. 0, Indian Point Unit 3 Boron Injection Tank Nozzle Environmental Fatigue Evaluations (Jun. 14, 2010) [PROPRIETARY]                 | 3/29/2012                      | X                                       |
| ENT000207                | NYS-26B/RK-TC-1B                                | Westinghouse Calculation Note Number CN-PAFM-09-13, Rev. 0, Indian Point Unit 3 BIT Nozzle Transfer Function Database Development (June 18, 2010) [PROPRIETARY]                             | 3/29/2012                      | X                                       |
| ENT000208                | NYS-26B/RK-TC-1B                                | F. Kreith, Principles of Heat Transfer (3rd ed. 1973) (excerpted)   | 3/29/2012                      | X                                       |
| ENT000209                | NYS-26B/RK-TC-1B                                | J. P. Holman, Heat Transfer (4th ed. 1976) (excerpted)  | 3/29/2012                      | X                                       |
| ENT000210                | NYS-26B/RK-TC-1B                                | Westinghouse, Systems Standard Design Criteria 1.3.F, Rev. 0, Reactor Coolant System Design Transients for Standard Plants with Model F Steam Generators (July 1978) [PROPRIETARY]          | 3/29/2012                      | X                                       |
| ENT000211                | NYS-26B/RK-TC-1B                                | Westinghouse Memorandum LTR-SSO-03-43, Rev. 1, from NS Systems & Safety Analysis, Design Transient Revisions for Indian Point 2 4.7% Uprate – Revised Figures (Apr. 25, 2003) [PROPRIETARY] | 3/29/2012                      | X                                       |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>  | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|--|--------------------------------|---|
| ENT000212                | NYS-26B/RK-TC-1B                                | Westinghouse Memorandum LTR-SCS-03-53, Rev. 0, from NS Systems & Safety Analysis, Design Transient Revisions for Indian Point 3 Stretch Power Uprate Project – Revised Figures (Aug. 21, 2003) [PROPRIETARY]   | 3/29/2012                      | X                                       |
| ENT000213                | NYS-26B/RK-TC-1B                                | Westinghouse, Systems Standard Design Criteria 1.3.X, Rev. 0, Nuclear Steam Supply System Auxiliary Equipment Design Transients for All Standard Plants (Sept. 1978) [PROPRIETARY]   | 3/29/2012                      | X                                       |
| ENT000214                | NYS-26B/RK-TC-1B                                | EPRI, Materials Reliability Program: Evaluation of Fatigue Data Including Reactor Water Environmental Effects (Dec. 2001)  | 3/29/2012                      | X                                       |
| ENT000215                | NYS-26B/RK-TC-1B                                | W. E. Cooper, The Initial Scope and Intent of the Section III Fatigue Design Procedures, in Pressure Vessel Research Council, Technical Information from Workshop on Cyclic Events in Nuclear Applications, Clearwater Beach, Florida, Vol. 1, (Jan. 20, 1992) | 3/29/2012                      | X                                       |
| ENT000216                | NYS-26B/RK-TC-1B                                | NUREG-1929, Safety Evaluation Report Related to the License Renewal of Beaver Valley Power Station, Units 1 and 2 (Oct. 2009) (excerpted)  | 3/29/2012                      | X                                       |
| ENT000217                | NYS-26B/RK-TC-1B                                | Westinghouse, WCAP-9693, Investigation of Feedwater Line Cracking in Pressurized Water Reactor Plants (June 1980) [PROPRIETARY] (excerpted)  | 3/29/2012                      | X                                       |
| ENT000218                | NYS-26B/RK-TC-1B                                | Westinghouse Owners Group, WCAP-12639, Pressurizer Surge Line Thermal Stratification Generic Detailed Analysis Program MUHP-1091 Summary Report (June 1990) [PROPRIETARY]  | 3/29/2012                      | X                                       |
| ENT000219                | NYS-26B/RK-TC-1B                                | Westinghouse, WCAP-12937, Structural Evaluation of Indian Point Units 2 and 3 Pressurizer Surge Lines, Considering the Effects of Thermal Stratification (May 1991) [PROPRIETARY]  | 3/29/2012                      | X                                       |

| Entergy Exhibit # | Track 2 Contentions Addressed by Exhibit | Exhibit Name  | Exhibit Submission Date | Admitted During Track 1 Hearing? |
|-------------------|--|---|-------------------------|----------------------------------|
| ENT000220         | NYS-26B/RK-TC-1B                         | J. D. Burr <i>et al.</i> , PVP2011-57700, Simulation and Evaluation of Thermal Stratification in a Sloped Surge Nozzle Correlated with Plant Measurements (July 2011) | 3/29/2012               | X                                |
| ENT000221         | NYS-26B/RK-TC-1B                         | M. E. Nitzel <i>et al.</i> , Comparison of ASME Code NB-3200 and NB-3600: Results for Fatigue Analysis of B31.1 Branch Nozzles (Apr. 1996)                            | 3/29/2012               | X                                |
| ENT000222         | NYS-26B/RK-TC-1B                         | Letter from Ekaterina Lenning, NRC, to James A Gresham, Westinghouse, "Westinghouse Electric Company Quality Management System, Revision 6" (Feb. 24, 2011)           | 3/29/2012               | X                                |
| ENT000223         | NYS-26B/RK-TC-1B                         | NUREG-1916, Safety Evaluation Report Related to the License Renewal of Shearon Harris Nuclear Power Plant, Unit 1, Vol. 2 (Nov. 2008) (excerpted)                     | 3/29/2012               | X                                |
| ENT000224         | NYS-26B/RK-TC-1B                         | SECY-95-245, Completion of the Fatigue Action Plan (Sept. 25, 1995)   | 3/29/2012               | X                                |
| ENT000225         | NYS-26B/RK-TC-1B                         | NUREG/CR-6815, Review of the Margins for ASME Code Fatigue Design Curve – Effects of Surface Roughness and Material Variability (Sept. 2003)                          | 3/29/2012               | X                                |
| ENT000226         | NYS-26B/RK-TC-1B                         | Entergy, 0-CY-2310, Rev. 16, Reactor Coolant System Specification and Frequencies (Oct. 2011)   | 3/29/2012               | X                                |
| ENT000227         | NYS-26B/RK-TC-1B                         | Westinghouse, WCAP-13588, Operating Strategies for Mitigating Pressurizer Insurge and Outsurge Transients (Mar. 1993) [PROPRIETARY] (excerpted)                       | 3/29/2012               | X                                |
| ENT000228         | NYS-26B/RK-TC-1B                         | Calculation Note RCDA-03-75, Indian Point Unit 3 Stretch Power Uprate Reactor Vessel Structural Evaluation (May 2005) [PROPRIETARY]                                   | 3/29/2012               | X                                |

| Entergy Exhibit # | Track 2 Contentions Addressed by Exhibit | Exhibit Name   | Exhibit Submission Date | Admitted During Track 1 Hearing? |
|-------------------|--|--|-------------------------|----------------------------------|
| ENT000229         | NYS-26B/RK-TC-1B                         | Calculation Note RCDA-03-64, Indian Point Unit 2 Stretch Power Uprate Reactor Vessel Evaluation (Feb. 2005) [PROPRIETARY]  | 3/29/2012               | X                                |
| ENT000230         | NYS-26B/RK-TC-1B, NYS-38/RK-TC-5, NYS-25 | Letter from R. Nelson, NRC, to N. Wilmshurst, EPRI, Revision 1 to the Safety Evaluation of Electric Power Research Institute (EPRI) Report, Materials Reliability Program (MRP) Report 1016596 (MRP-227), Revision 0, Pressurized Water Reactor (PWR) Internals Inspection and Evaluation Guidelines (Dec. 16, 2011) | 3/29/2012               | X                                |
| ENT000231         | NYS-26B/RK-TC-1B, NYS-25                 | NL-08-143, Letter from F. Dacimo, Entergy, to NRC, Additional Information (Regarding License Renewal Application – Reactor Vessel Fluence Clarification (Sept. 24, 2008)   | 3/29/2012               | X                                |
| ENT000251         | NYS-38/RK-TC-5                           | NRC Inspection Manual Chapter 71003, Post-Approval Site Inspection for License Renewal (Oct. 31, 2008)   | 3/29/2012               | X                                |
| ENT000252         | NYS-38/RK-TC-5                           | NRC Inspection Manual, Temporary Instruction 2516/001 (Mar. 30, 2011)  | 3/29/2012               | X                                |
| ENT000369         | NYS-26B/RK-TC-1B                         | Entergy Nuclear Vt. Yankee (Vt. Yankee Nuclear Power Station), Docket No. 50-271-LR, Hearing Transcript (Jul. 21, 2008) (excerpted)  | 3/29/2012               | X                                |
| ENT000520         | NYS-38/RK-TC-5                           | Entergy Statement of Position Regarding Contention NYS-38/RK-TC-5 (Safety Commitments)   | 8/20/2012               | X                                |
| ENT000521         | NYS-38/RK-TC-5                           | Direct Testimony of Entergy Witnesses Nelson F. Azevedo, Robert J. Dolansky, Alan B. Cox, Jack R. Strosnider, Robert E. Nickell, and Mark A. Gray Regarding Contention NYS-38/RK-TC-5 (Safety Commitments)   | 8/20/2012               | X                                |
| ENT000522         | NYS-38/RK-TC-5, NYS-25                   | <i>Curriculum Vitae</i> of Robert J. Dolansky  | 8/20/2012               | X                                |



| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENT000523                | NYS-38/RK-TC-5                                  | EPRI, Report No. 1020988, “Steam Generator Management Program: Phase II Divider Plate Cracking Engineering Study” (Nov. 2010) [PROPRIETARY]   | 8/20/2012                      | X                                       |
| ENT000524                | NYS-38/RK-TC-5                                  | EPRI, Report 1025133, Steam Generator Management Program: Assessment of Channel Head Susceptibility to Primary Water Stress Corrosion Cracking (June 2012) [PROPRIETARY]  | 8/20/2012                      | X                                       |
| ENT000525                | NYS-38/RK-TC-5                                  | NRC Inspection Manual Chapter 2516 (Feb. 18, 2005)  | 8/20/2012                      | X                                       |
| ENT000526                | NYS-38/RK-TC-5                                  | F. D’Annunci and E. Lecour, ICONE18-29457, Inspection of the Steam Generator Divider Plate (May 2010)   | 8/20/2012                      | X                                       |
| ENT000527                | NYS-38/RK-TC-5                                  | NRC Information Notice 2005-09, Indications in Thermally Treated Alloy 600 Steam Generator Tubes and Tube-to Tubesheet Welds (Apr. 7, 2005)   | 8/20/2012                      | X                                       |
| ENT000528                | NYS-38/RK-TC-5                                  | NUREG-1950, Disposition of Public Comments and Technical Bases for Changes in the License Renewal Guidance Documents NUREG-1801 and NUREG-1800 (Apr. 2011) (excerpted)  | 8/20/2012                      | X                                       |
| ENTR00529                | NYS-38/RK-TC-5                                  | Westinghouse Technical Manual No. TMMC 1440-C350, Vertical Steam Generator Instruction for New York Power Authority - Indian Point Nuclear Plant No. 3 (Dec. 1989) [PROPRIETARY] (excerpted)  | 8/10/2015                      | [Revised]                               |
| ENT000530                | NYS-38/RK-TC-5                                  | EPRI, Report 1014982, Divider Plate Cracking in Steam Generators – Results of Phase 1: Analysis of Primary Water Stress Corrosion Cracking and Mechanical Fatigue in the Alloy 600 Stub Runner to Divider Plate Weld Material (June 2007) [PROPRIETARY] | 8/20/2012                      | X                                       |
| ENT000531                | NYS-38/RK-TC-5                                  | ASME Code, Sec. XI, Art. IWA-2000 (2001)  | 8/20/2012                      | X                                       |
| ENT000532                | NYS-38/RK-TC-5                                  | ASME Code, Sec. V, Art. 14 (2001)   | 8/20/2012                      | X                                       |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>  | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|--|--------------------------------|---|
| ENT000533                | NYS-38/RK-TC-5                                  | Memorandum from C. Hunt, NRC to G. Kulesa, NRC, "Summary of the February 16, 2012, Category 2 Public Meeting with the Electric Power Research Institute (EPRI) and Industry to Discuss Steam Generator Issues" (Mar. 15, 2012) | 8/20/2012                      | X                                       |
| ENT000534                | NYS-38/RK-TC-5                                  | NEI 99-04, Guidelines for Managing NRC Commitment Changes (July 1999)  | 8/20/2012                      | X                                       |
| ENT000535                | NYS-38/RK-TC-5                                  | NRR Office Instruction, LIC-105, Rev. 3, Managing Regulatory Commitments Made by Licensees to the NRC (Mar. 2009)  | 8/20/2012                      | X                                       |
| ENT000536                | NYS-38/RK-TC-5                                  | NUREG-2101, Safety Evaluation Report Related to the License Renewal of Salem Nuclear Generating Station (June 2011) (excerpted)  | 8/20/2012                      | X                                       |
| ENT000537                | NYS-38/RK-TC-5                                  | NUREG-1961, Safety Evaluation Report Related to the License Renewal of Palo Verde Nuclear Generating Station, Units 1, 2, and 3 (Apr. 2011) (excerpted)  | 8/20/2012                      | X                                       |
| ENT000538                | NYS-38/RK-TC-5                                  | SECY 2000-45, Acceptance of NEI 99-04, "Guidelines for Managing NRC Commitments" (Feb. 22, 2000)   | 8/20/2012                      | X                                       |
| ENT000539                | NYS-38/RK-TC-5                                  | NRC Enforcement Manual, Rev. 7 (Oct. 1, 2010) (excerpted)  | 8/20/2012                      | X                                       |
| ENT000540                | NYS-38/RK-TC-5                                  | Entergy Nuclear Generation Co. (Pilgrim Nuclear Power Station) Docket No. 50-293, Renewed Facility Operating License (May 9, 2012) (excerpted)   | 8/20/2012                      | X                                       |
| ENT000541                | NYS-38/RK-TC-5                                  | EN-LI-110, Commitment Management Program (Jan. 2012)   | 8/20/2012                      | X                                       |
| ENT000542                | NYS-38/RK-TC-5                                  | NRC Regulatory Issue Summary 2000-17, Managing Regulatory Commitments Made by Power Reactor Licensees to the NRC Staff (Sept. 21, 2000)  | 8/20/2012                      | X                                       |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENT000543                | NYS-38/RK-TC-5                                  | Inspection Procedure 71002, License Renewal Inspection (Nov. 2011)  | 8/20/2012                      | X                                       |
| ENT000544                | NYS-38/RK-TC-5                                  | Letter from A. Macfarlane, Chairman, NRC, to E. Markey, U.S. Congressman, "Regulatory Commitments" (July 12, 2012)  | 8/20/2012                      | X                                       |
| ENT000545                | NYS-38/RK-TC-5                                  | Memorandum from S. Dingbaum, Assistant Inspector Gen. for Audits, NRC, to R. W. Borchardt, Exec. Dir. for Operations, NRC, "Status of Recommendations: Audit of NRC's Management of Licensee Commitments (OIG-11-A-17)" (Apr. 16, 2012)                 | 8/20/2012                      | X                                       |
| ENT000546                | NYS-38/RK-TC-5                                  | NUREG-1958, Safety Evaluation Report Related to the License Renewal of Kewaunee Power Station (Jan. 2011) (excerpted)   | 8/20/2012                      | X                                       |
| ENT000547                | NYS-38/RK-TC-5                                  | EA-12-051, Order Modifying Licenses With Regard to Reliable Spent Fuel Pool Instrumentation (Effective Immediately) (Mar. 12, 2012)   | 8/20/2012                      | X                                       |
| ENT000548                | NYS-38/RK-TC-5                                  | Letter from R. Braun, Senior Vice President, PSEG Nuclear LLC, to NRC Document Control Desk, "PSEG Nuclear LLC's Response to March 12, 2012 Commission Order Modifying License with Regard to Reliable Spent Fuel Pool Instrumentation" (Mar. 29, 2012) | 8/20/2012                      | X                                       |
| ENT000549                | NYS-38/RK-TC-5                                  | Letter from R. Conte, NRC, to J. Ventosa, Entergy, "Indian Point Nuclear Generating Unit 2 – NRC Inspection Report 05000247/2012008" (Apr. 19, 2012)  | 8/20/2012                      | X                                       |
| ENT000550                | NYS-38/RK-TC-5, NYS-26B/RK-TC-1B                | Letter from A. Cunanan, NRC Project Manager, to S.K. Gambhir, Vice President, Energy Northwest, "Request for Additional Information for the Review of the Columbia Generating Station License Renewal Application for Metal Fatigue" (Feb. 3, 2011)     | 8/20/2012                      | X                                       |
| ENT000551                | NYS-38/RK-TC-5                                  | Letter from B. Harris, NRC Project Manager, to B. Allen, FENOC, "Request for Additional Information for the Review of the Davis-Besse Nuclear Power Station – Batch 3" (May 2, 2011) (excerpted)  | 8/20/2012                      | X                                       |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENT000552                | NYS-38/RK-TC-5                                  | Letter from P. Bessette, Morgan Lewis, to Administrative Judges (May 15, 2012)  | 8/20/2012                      | X                                       |
| ENT000553                | NYS-38/RK-TC-5                                  | Entergy, Condition Report LO-LAR-2011-00174, Corrective Actions (Aug. 2011) (excerpted)   | 8/20/2012                      | X                                       |
| ENT000554                | NYS-38/RK-TC-5, NYS-26B/RK-TC-1B                | NL-12-089, Letter from F. Dacimo, Entergy, to NRC, "Reply to Request for Additional Information Regarding the License Renewal Application Indian Point Nuclear Generating Unit Nos. 2 & 3" (June 14, 2011)                                | 8/20/2012                      | X                                       |
| ENT000555                | NYS-38/RK-TC-5                                  | B. Gordon, Minimum Chromium Content In Nickel-Alloy Weld Overlays to Mitigate PWSCC (Jan. 18, 2005)   | 8/20/2012                      | X                                       |
| ENT000556                | NYS-38/RK-TC-5                                  | F. Delabrouille et al., Effect of the Chromium Content and Strain on the Corrosion of Nickel Based Alloys in Primary Water of Pressurized Water Reactors (2005)   | 8/20/2012                      | X                                       |
| ENT000557                | NYS-38/RK-TC-5                                  | EPRI, Report 1014986, Pressurized Water Reactor Primary Water Chemistry Guidelines, Rev. 6 (Dec. 2007) [PROPRIETARY] (excerpted)  | 8/20/2012                      | X                                       |
| ENT000558                | NYS-38/RK-TC-5                                  | Letter from J. Daily, Project Manager, NRC, to D. Heacock, President, Dominion Energy Kewaunee, "Request for Additional Information for the Review of the Kewaunee Power Station License Renewal Application" (Mar. 11, 2010)             | 8/20/2012                      | X                                       |
| ENT000559                | NYS-38/RK-TC-5                                  | Letter from B. Brady, Project Manager, NRC, to T. Joyce, President, PSEG Nuclear, "Request for Additional Information for Salem Nuclear Generating Stations Units 1 and 2 License Renewal Application" (June 10, 2010)                    | 8/20/2012                      | X                                       |
| ENT000560                | NYS-38/RK-TC-5                                  | Letter from R. Plasse, Project Manager, NRC, to P. Freeman, Site Vice President, NextEra Energy Seabrook, "Request for Additional Information Related to the Review of the Seabrook Station, License Renewal Application" (Dec. 14, 2010) | 8/20/2012                      | X                                       |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>  | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|--|--------------------------------|---|
| ENT000561                | NYS-38/RK-TC-5                                  | Kewaunee Tr., Advisory Comm. on Reactor Safeguards, Plant License Renewal Subcomm. (Aug. 18, 2010) (excerpted)   | 8/20/2012                      | X                                       |
| ENT000562                | NYS-38/RK-TC-5                                  | Letter from J. Daily, NRC, to D. Heacock, President, Dominion Energy Kewaunee, Inc., "Request for Additional Information for the Review of the Kewaunee Power Station License Renewal Application (TAC No. MD9408)" (Sept. 10, 2010) | 8/20/2012                      | X                                       |
| ENT000563                | NYS-38/RK-TC-5                                  | Letter from Said Abdel-Khalik, ACRS Chairman, to Jaczko, NRC Chairman, "Report on the Safety Aspects of the License Renewal Application for the Kewaunee Power Station" (Jan. 7, 2011)   | 8/20/2012                      | X                                       |
| ENT000564                | NYS-38/RK-TC-5                                  | Final License Renewal Interim Staff Guidance, LR-ISG-2011-05, "Ongoing Review of Operating Experience" (Mar. 9, 2012)  | 8/20/2012                      | X                                       |
| ENT000565                | NYS-38/RK-TC-5                                  | Letter from L. Hartz, Vice President, Dominion Energy Kewaunee., to, NRC, "Response to Request for Additional Information for the Review of the Kewaunee Power Station License Renewal Application" (Sept. 23, 2010)                 | 8/20/2012                      | X                                       |
| ENT000566                | NYS-38/RK-TC-5                                  | Letter from P. Freeman, Site Vice President, NextEra Energy Seabrook, to NRC, "Response to Request for additional Information – Set 10" (Mar. 22, 2011)  | 8/20/2012                      | X                                       |
| ENT000567                | NYS-38/RK-TC-5                                  | NL-00-043, Letter from J. Baumstark, Consol. Edison Co. of N.Y., to NRC, "Root Cause Evaluation For Steam Generator Tube Rupture Event of February 15, 2000" (Apr. 14, 2000)   | 8/20/2012                      | X                                       |
| ENT000568                | NYS-38/RK-TC-5                                  | EPRI, Report 1019044, Steam Generator Management Program: Improvement Factors for Pressurized Water Reactor Steam Generator Tube Materials (Dec. 2009) [PROPRIETARY] (excerpted)   | 8/20/2012                      | X                                       |
| ENT000569                | NYS-38/RK-TC-5                                  | Letter from E. Shields, Westinghouse, to W. Wittich, Entergy, "Steam Generator Operational Assessment" (June 29, 2010) [PROPRIETARY]   | 8/20/2012                      | X                                       |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>  | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|--|--------------------------------|---|
| ENT000570                | NYS-38/RK-TC-5                                  | WCAP-17091-NP, Rev. 0, H*, Alternate Repair Criteria for the Tubesheet Expansion Region in Steam Generators with Hydraulically Expanded Tubes (Model 44F) (June 2009) (excerpted)                  | 8/20/2012                      | X                                       |
| ENT000571                | NYS-38/RK-TC-5                                  | Safety Evaluation Related to Amendment No. 308 for Oconee Nuclear Station Units 1, 2 and 3 (Dec. 3, 1999)  | 8/20/2012                      | X                                       |
| ENT000572                | NYS-38/RK-TC-5                                  | Letter from A. Cunanan, NRC, to M. Reddemann, Energy Northwest, "Issuance of Renewed Facility Operating License No. NPF-21 for Columbia Generating Station" (May 22, 2012) (ENT000540) (excerpted) | 8/20/2012                      | X                                       |
| ENT000602                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | EN-LI-100, Rev. 12, Process Applicability Determination (Nov. 6, 2012)   | 1/11/2013                      | X                                       |
| ENT000603                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | EN-LI-101, Rev. 9, 10 CFR 50.59 Evaluations (Feb. 16, 2012)  | 1/11/2013                      | X                                       |
| ENT000604                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Indian Point Nuclear Generating Units 2 and 3, NRC Evaluation of Changes, Tests or Experiments and Permanent Plant Modifications Team Inspection Report (Jan. 13, 2012)                            | 1/11/2013                      | X                                       |
| ENT000615                | NYS-25  | Entergy's Statement of Position Regarding Contention NYS-25 (Embrittlement) (Aug. 10, 2015)  | 8/10/2015                      |   |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENT000616                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Testimony of Entergy Witnesses Nelson F. Azevedo, Robert J. Dolansky, Alan B. Cox, Jack R. Strosnider, Timothy J. Griesbach, Randy G. Lott, and Mark A. Gray Regarding Contention NYS-25 (Embrittlement) (Aug. 10, 2015)  | 8/10/2015                      |   |
| ENT000617                | NYS-25, NYS-38/RK-TC-5                          | <i>Curriculum Vitae</i> of Timothy J. Griesbach   | 8/10/2015                      |   |
| ENT000618                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | <i>Curriculum Vitae</i> of Randy G. Lott  | 8/10/2015                      |   |
| ENT000619                | NYS-25  | NL-08-127, Letter from F. Dacimo, Entergy, to NRC Document Control Desk, “Additional Information Regarding License Renewal Application – Structural OE Clarifications, Clarifications for Electrical RAIs and Audit Questions, License Renewal Application Amendment” (Aug. 14, 2008) | 8/10/2015                      |   |
| ENT000620                | NYS-25, NYS-38/RK-TC-5                          | PWROG Presentation, “Material Orientation Toughness Assessment (MOTA) for the Purpose of Mitigating Branch Technical Position (BTP) 5-3 Uncertainties” (Feb. 19, 2015)  | 8/10/2015                      |   |
| ENT000621                | NYS-25, NYS-38/RK-TC-5                          | Westinghouse, WCAP-17894-NP, Rev. 0, Component Inspection Details Supporting Aging Management of Reactor Internals at Indian Point Unit 2 (Sept. 2014)  | 8/10/2015                      |   |
| ENT000622                | NYS-25, NYS-38/RK-TC-5                          | Westinghouse, WCAP-17901-NP, Rev. 1, Component Inspection Details Supporting Aging Management of Reactor Internals at Indian Point Unit 3 (Sept. 2014)  | 8/10/2015                      |   |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENT000623                | NYS-25,<br>NYS-38/RK-TC-5                       | Cases of ASME Boiler and Pressure Vessel Code, Case N-729-1, “Alternative Examination Requirements for PWR Reactor Vessel Upper Heads With Nozzles Having Pressure-Retaining Partial-Penetration Welds,” (Section XI, Division 1) (Mar. 28, 2006) [Full-Text Copyright]                           | 8/10/2015                      |   |
| ENT000624                | NYS-25,<br>NYS-38/RK-TC-5                       | Letter from N. Salgado to Vice President, Operations, Entergy Nuclear Operations, Inc., “Indian Point Nuclear Generating Unit No. 2 – Relief from the Examination Area for Reactor Vessel Head Penetration Nozzles (TAC No. ME1658)” (Mar. 1, 2010)   | 8/10/2015                      |   |
| ENT000625                | NYS-25,<br>NYS-38/RK-TC-5                       | Letter from N. Salgado to Vice President, Operations, Entergy Nuclear Operations, Inc., “Indian Point Nuclear Generating Unit No. 3 – Relief Requests RR-3-45 and RR-3-46 for Reactor Vessel Head Penetrations Examination (TAC Nos. ME0411 and ME0412)” (July 8, 2009)                           | 8/10/2015                      |   |
| ENT000626                | NYS-25,<br>NYS-38/RK-TC-5                       | Letter from P. Milano, NRC, to M. Kansler, Entergy, “Bulletin 2002-01, ‘Reactor Pressure Vessel Head Degradation and Reactor Coolant Pressure Boundary Integrity,’ 15-Day Response for Indian Pont Nuclear Generating Unit Nos. 2 & 3 (TAC Nos. MB4550 and MB4551)” (Nov. 12, 2002) (ENT-25-0026) | 8/10/2015                      |   |
| ENT000627                | NYS-25,<br>NYS-26B/RK-TC-1B, NYS-38/RK-TC-5     | G. Was, Fundamentals of Radiation Materials Science: Metals and Alloys; Part III: Mechanical Effects of Radiation Damage (2007) [Full-Text Copyright] [excerpt]   | 8/10/2015                      |   |
| ENT000628                | NYS-25,<br>NYS-38/RK-TC-5                       | I. Tylek and K. Kuchta, Mechanical Properties of Structural Stainless Steels, 4-B Technical Transactions, Civil Engineering 59 (2014) [Full-Text Copyright]   | 8/10/2015                      |   |



| Entergy Exhibit # | Track 2 Contentions Addressed by Exhibit | Exhibit Name  | Exhibit Submission Date | Admitted During Track 1 Hearing? |
|-------------------|--|---|-------------------------|----------------------------------|
| ENT000629         | NYS-25, NYS-38/RK-TC-5                   | Letter from C. Grimes, NRC, to D. Walters, NEI, "License Renewal Issue No. 98-0030, 'Thermal Aging Embrittlement of Cast Austenitic Stainless Steel Components'" (May 19, 2000)                                 | 8/10/2015               |                                  |
| ENT000630         | NYS-25, NYS-38/RK-TC-5                   | W.J. Mills, Effect of Temperature on the Fracture Toughness Behavior of Inconel X-750, in ASTM STP 733: Fractography and Materials Science 98 (L.N. Gilbertson and R.D. Zipp, eds., 1981) [Full-Text Copyright] | 8/10/2015               |                                  |
| ENT000631         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | EPRI, MRP-175, Materials Reliability Program: PWR Internals Material Aging Degradation Mechanism Screening and Threshold Values (Dec. 2005) [Full-Text Copyright]   | 8/10/2015               |                                  |
| ENT000632         | NYS-25, NYS-38/RK-TC-5                   | ASME Boiler & Pressure Vessel Code, Section III, Article NB-2000, "Material" (1998) [Full-Text Copyright]   | 8/10/2015               |                                  |
| ENT000633         | NYS-25, NYS-38/RK-TC-5                   | Letter from P. Anderson, Entergy, to NRC Document Control Desk, "Documentation for Pressurized Thermal Shock Evaluation Meeting" (June 2, 2010)   | 8/10/2015               |                                  |
| ENT000634         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Entergy, IP2, FSAR Update, Revision 25 (2014) [excerpts]  | 8/10/2015               |                                  |
| ENT000635         | NYS-25, NYS-38/RK-TC-5                   | Westinghouse, WCAP-17096-NP, Rev. 2, Reactor Internals Acceptance Criteria Methodology and Data Requirements (Dec. 2009)  | 8/10/2015               |                                  |

| Entergy Exhibit # | Track 2 Contentions Addressed by Exhibit | Exhibit Name  | Exhibit Submission Date | Admitted During Track 1 Hearing? |
|-------------------|--|---|-------------------------|----------------------------------|
| ENT000636         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | P. Shahinian et al., NRL Report 7446, Effect of Neutron Irradiation on Fatigue Crack Propagation in Types 304 and 316 Stainless Steels at High Temperature (July 21, 1972)          | 8/10/2015               |                                  |
| ENT000637         | NYS-25, NYS-38/RK-TC-5                   | NUREG-1874, Recommended Screening Limits for Pressurized Thermal Shock (PTS) (March 2010)   | 8/10/2015               |                                  |
| ENT00638A-C       | NYS-25, NYS-38/RK-TC-5                   | NUREG-1806, Vol. 1, Technical Basis for Revision of the Pressurized Thermal Shock (PTS) Screening Limit in the PTS Rule (10 CFR 50.61) (Aug. 2007)                                  | 8/10/2015               |                                  |
| ENT00639A-F       | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Westinghouse, WCAP-16156, Indian Point Nuclear Generating Unit No. 2, Stretch Power Uprate NSSS Engineering Report (Mar. 2004) [PROPRIETARY]  | 8/10/2015               |                                  |
| ENT00640A-I       | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Westinghouse, WCAP-16211, Power Uprate Project, Indian Point Unit 3 Power Plant, NSSS Engineering Report (June 2004) [PROPRIETARY]  | 8/10/2015               |                                  |
| ENT000641         | NYS-25, NYS-38/RK-TC-5                   | Final License Renewal Interim Staff Guidance LR-ISG-2011-04, Updated Aging Management Criteria for Reactor Vessel Internal Components for Pressurized Water Reactors (May 28, 2013) | 8/10/2015               |                                  |
| ENT00642A-C       | NYS-25, NYS-38/RK-TC-5                   | EPRI, MRP-232, Materials Reliability Program: Aging Management Strategies for Westinghouse and Combustion Engineering PWR Internals (Dec. 2008) [Full-Text Copyright]               | 8/10/2015               |                                  |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>  | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|--|--------------------------------|---|
| ENT000643                | NYS-25,<br>NYS-38/RK-TC-5                       | EPRI, MRP-232, Revision 1, Materials Reliability Program: Aging Management Strategies for Westinghouse and Combustion Engineering PWR Internals (Dec. 2008) [Full-Text Copyright]  | 8/10/2015                      |   |
| ENT000644                | NYS-25,<br>NYS-38/RK-TC-5                       | EPRI, MRP-230, Materials Reliability Program: Functionality Analysis for Westinghouse and Combustion Engineering Representative PWR Internals (Oct. 2009) [Full-Text Copyright]  | 8/10/2015                      |   |
| ENT000645                | NYS-25,<br>NYS-38/RK-TC-5                       | EPRI, MRP-228, Rev. 1, Materials Reliability Program: Inspection Standard for PWR Internals – 2012 Update (Dec. 2012) [Full-Text Copyright]  | 8/10/2015                      |   |
| ENT000646                | NYS-25,<br>NYS-26B/RK-TC-1B, NYS-38/RK-TC-5     | EPRI, MRP-210, Materials Reliability Program: Fracture Toughness Evaluation of Highly Irradiated PWR Stainless Steel Internal Components (Dec. 2007) [Full-Text Copyright]   | 8/10/2015                      |   |
| ENT000647                | NYS-25,<br>NYS-38/RK-TC-5                       | EPRI, MRP-134, Materials Reliability Program: Framework and Strategies for Managing Aging Effects in PWR Internals (June 2005) [Full-Text Copyright]   | 8/10/2015                      |   |
| ENT000648                | NYS-25,<br>NYS-38/RK-TC-5                       | M. Mitchell, Chief, Vessels and Internals Integrity Branch, Response to Non-Concurrence Regarding Safety Evaluation for Topical Report MRP-227, “Pressurized Water Reactor Internals Inspection and Evaluation Guidelines” (undated)               | 8/10/2015                      |   |
| ENT000649                | NYS-25,<br>NYS-38/RK-TC-5                       | Letter from D. Pelton, NRC, to E. McCartney, NextEra Energy Point Beach, “Point Beach Nuclear Plant, Units 1 and 2 – Staff Assessment of Reactor Vessel Internals Inspection Plan Based on MRP-227-A (TAC Nos. ME8235 and ME8236)” (Mar. 30, 2015) | 8/10/2015                      |   |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENT000650                | NYS-25,<br>NYS-38/RK-<br>TC-5                   | G. Gardner, Chair, EPRI Reactor Internals Working Group, Recent Materials Inspections of PWR Reactor Internals (Mar. 2015)  | 8/10/2015                      |   |
| ENT000651                | NYS-25,<br>NYS-38/RK-<br>TC-5                   | T. Griesbach and B. Gordon, Materials Aging Management Programs at Nuclear Power Plants in the United States (Oct. 2007) [Full-Text Copyright]  | 8/10/2015                      |   |
| ENT000652                | NYS-25,<br>NYS-38/RK-<br>TC-5                   | Letter from P. Milano, NRR, to M. Kansler, Entergy, “Indian Point Nuclear Generating Unit No. 2 - Issuance of Amendment Re: 3.26 Percent Power Uprate (TAC No. MC1865)” (Oct. 27, 2004)   | 8/10/2015                      |   |
| ENT000653                | NYS-25,<br>NYS-38/RK-<br>TC-5                   | Letter from P. Milano, NRR, to M. Kansler, Entergy, “Indian Point Nuclear Generating Unit No. 3 - Issuance of Amendment Re: 4.85 Percent Stretch Power Uprate and Relocation of Cycle-Specific Parameters (TAC No. MC3552)” (Mar. 24, 2005) | 8/10/2015                      |   |
| ENT000654                | NYS-25,<br>NYS-38/RK-<br>TC-5                   | Westinghouse, WCAP-15270, Determination of Acceptable Baffle-Barrel-Bolting for Four-Loop Westinghouse Downflow and Converted Upflow Domestic Plants (Nov. 2001) [PROPRIETARY]  | 8/10/2015                      |   |
| ENT000655                | NYS-25,<br>NYS-38/RK-<br>TC-5                   | Westinghouse, WCAP-15030-NP-A, Westinghouse Methodology for Evaluating the Acceptability of Baffle-Former-Barrel Bolting Distributions under Faulted Load Conditions (Mar. 2, 1999)   | 8/10/2015                      |   |
| ENT000656                | NYS-25,<br>NYS-38/RK-<br>TC-5                   | Westinghouse, Technical Bulletin TB-14-5, Reactor Internals Lower Radial Support Clevis Insert Cap Screw Degradation (Aug. 25, 2014)  | 8/10/2015                      |   |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENT000657                | NYS-25,<br>NYS-38/RK-TC-5                       | NRC Inspection Manual, Manual Chapter 2516, Policy and Guidance for the License Renewal Inspection Program (“LRIP”) (Aug. 13, 2013)   | 8/10/2015                      |   |
| ENT000658                | NYS-25,<br>NYS-38/RK-TC-5                       | J. Smith, Irradiated Materials Testing, Inside MRP (Winter 2012)  | 8/10/2015                      |   |
| ENT000659                | NYS-25,<br>NYS-26B/RK-TC-1B, NYS-38/RK-TC-5     | Letter from R. Kuntz, NRC, to Vice President, Operations, Entergy, “Request for Additional Information for the Review of the Indian Point Nuclear Generating Unit Nos. 2 and 3, License Renewal Application” (May 15, 2012)   | 8/10/2015                      |   |
| ENT000660                | NYS-25,<br>NYS-38/RK-TC-5                       | Letter from J. Daly, NRC, to Vice President, Operations, Entergy, “Request for Additional Information for the Review of the Indian Point Nuclear Generating Unit Nos. 2 and 3 License Renewal Application, Set 2013-01 (TAC Nos. MD5407 and MD5408)” (Feb. 6, 2013)   | 8/10/2015                      |   |
| ENT000661                | NYS-25,<br>NYS-38/RK-TC-5                       | Letter from K. Green, NRC, to Vice President, Operations, Entergy, “Request for Additional Information for the Review of the Indian Point Nuclear Generating Unit Nos. 2 and 3 License Renewal Application, Set 2013-04 (TAC Nos. MD5407 and MD5408)” (July 26, 2013) | 8/10/2015                      |   |
| ENT000662                | NYS-25,<br>NYS-38/RK-TC-5                       | Letter from K. Green, NRC, to Vice President, Operations, Entergy, “Request for Additional Information for the Review of the Indian Point Nuclear Generating Unit Nos. 2 and 3 License Renewal Application, Set 2014-02 (TAC Nos. MD5407 and MD5408)” (Apr. 9, 2014)  | 8/10/2015                      |   |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>  | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|--|--------------------------------|---|
| ENT000663                | NYS-25, NYS-38/RK-TC-5                          | Letter from A. McGehee & T. Hanley, EPRI, to NRC Document Control Desk, BWRVIP 2015-025, "Project No. 704 – Summary of Industry Position on Screening Criteria for Thermal and Irradiation Embrittlement for PWR and BWR Reactor Internals Fabricated of Cast Austenitic Stainless Steel" (Mar. 9, 2015) | 8/10/2015                      |   |
| ENT000664                | NYS-25, NYS-38/RK-TC-5                          | Email from J. Holonich, NRC, to K. Amberge, EPRI, et al., "Summary Tables for CASS Position" (Mar. 12, 2014, 1:23 PM)  | 8/10/2015                      |   |
| ENT000665                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | ASME Boiler & Pressure Vessel Code, Section XI, Subsection IWB, "Requirements for Class 1 Components of Light-Water Cooled Plants" (2010) [Full-Text Copyright]  | 8/10/2015                      |   |
| ENT00666A-I              | NYS-25, NYS-38/RK-TC-5                          | NUREG/CR-6943, A Study of Remote Visual Methods to Detect Cracking in Reactor Components (Oct. 2007)   | 8/10/2015                      |   |
| ENT000667                | NYS-25, NYS-38/RK-TC-5                          | PWROG-14048-P, Rev. 0-A, PWROG, Functionality Analysis: Lower Support Columns (Oct. 2014) [PROPRIETARY]  | 8/10/2015                      |   |
| ENT000668                | NYS-25, NYS-38/RK-TC-5                          | EPRI, MRP-219, Rev. 10, Materials Reliability Program: Inspection Data Survey Report (Nov. 2014) [Full-Text Copyright]   | 8/10/2015                      |   |

| Entergy Exhibit # | Track 2 Contentions Addressed by Exhibit | Exhibit Name  | Exhibit Submission Date | Admitted During Track 1 Hearing? |
|-------------------|--|---|-------------------------|----------------------------------|
| ENT000669         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Regulatory Guide 1.99, Radiation Embrittlement of Reactor Vessel Materials, Revision 2 (May 1988)   | 8/10/2015               |                                  |
| ENT000670         | NYS-25                                   | NL-13-106, Letter from J. Ventosa, Entergy, to NRC Document Control Desk, "Proposed Revision to Reactor Vessel Surveillance Capsule Withdrawal Schedule Per 10 CFR 50 Appendix H" (Aug. 12, 2013)   | 8/10/2015               |                                  |
| ENT000671         | NYS-25                                   | NL-14-129, Letter from J. Ventosa, Entergy, to NRC Document Control Desk, "Proposed Revision to Reactor Vessel Surveillance Capsule Withdrawal Schedule Per 10 CFR 50 Appendix H" (Nov. 5, 2014)  | 8/10/2015               |                                  |
| ENT000672         | NYS-25                                   | Letter from B. Beasley, NRC, to Vice President, Operations, "Indian Point Nuclear Generating Unit No. 2 – Safety Evaluation re: Revision to the Reactor Vessel Surveillance Capsule Withdrawal Schedule per 10 CFR 50 Appendix H (TAC No. MF2558)" (Jan. 14, 2014)                          | 8/10/2015               |                                  |
| ENT000673         | NYS-25                                   | Letter from B. Beasley, NRC, to Vice President, Operations, "Indian Point Nuclear Generating Unit No. 3 – Safety Evaluation re: Revision to the Reactor Vessel Surveillance Capsule Withdrawal Schedule per 10 CFR 50 Appendix H (TAC No. MF5148)" (Mar. 4, 2015)                           | 8/10/2015               |                                  |
| ENT000674         | NYS-25                                   | NL-08-014, Letter from Fred R. Dacimo, Entergy, to NRC Document Control Desk, "Clarifications to Reactor Vessel Surveillance Program and Neutron Embrittlement Time-Limited Aging Analyses and Audit Item #105; and Revision to License Renewal Regulatory Commitment List" (Jan. 17, 2008) | 8/10/2015               |                                  |

| Entergy Exhibit # | Track 2 Contentions Addressed by Exhibit | Exhibit Name   | Exhibit Submission Date | Admitted During Track 1 Hearing? |
|-------------------|--|--|-------------------------|----------------------------------|
| ENT000675         | NYS-25                                   | Letter from M. Hodges, NRC, to W. Rasin, Nuclear Management and Resources Council, "Safety Assessment of Report WCAP-13587, Revision 1, 'Reactor Vessel Upper Shelf Energy Bounding Evaluation for Westinghouse Pressurized Water Reactors,' September 1993" (Apr. 21, 1994) | 8/10/2015               |                                  |
| ENT000676         | NYS-25                                   | NUREG-1785, Safety Evaluation Report Related to the License Renewal of H.B. Robinson Steam Electric Plant, Unit 2 (Mar. 2004)  | 8/10/2015               |                                  |
| ENT000677         | NYS-25                                   | NL-07-140, Letter from F. Dacimo, Entergy, to NRC Document Control Desk, "Reply to Request for Additional Information Regarding License Renewal Application" (Nov. 28, 2007)   | 8/10/2015               |                                  |
| ENT000678         | NYS-26B/RK-TC-1B                         | Entergy's Revised Statement of Position Regarding Contention NYS-26B/RK-TC-1B (Metal Fatigue) (Aug. 10, 2015)  | 8/10/2015               |                                  |
| ENT000679         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Revised Testimony of Entergy Witnesses Nelson F. Azevedo, Alan B. Cox, Jack R. Strosnider, Randy G. Lott, Mark A. Gray, and Barry M. Gordon Regarding Contention NYS-26B/RK-TC-1B (Metal Fatigue) (Aug. 10, 2015)  | 8/10/2015               |                                  |
| ENT000680         | NYS-26B/RK-TC-1B, NYS-38/RK-TC-5         | <i>Curriculum Vitae</i> of Barry M. Gordon   | 8/10/2015               |                                  |
| ENTR00681         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Westinghouse, WCAP-17199-P, Rev. 2, Environmental Fatigue Evaluation for Indian Point Unit 2 (Oct. 2015) [PROPRIETARY]   | 11/11/2015              |                                  |



| Entergy Exhibit # | Track 2 Contentions Addressed by Exhibit | Exhibit Name   | Exhibit Submission Date | Admitted During Track 1 Hearing? |
|-------------------|--|--|-------------------------|----------------------------------|
| ENTR00682         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Westinghouse, WCAP-17200-P, Rev. 2, Environmental Fatigue Evaluation for Indian Point Unit 3 (Oct. 2015) [PROPRIETARY]   | 11/11/2015              |                                  |
| ENTR00683         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Westinghouse, Calculation Note CN-PAFM-13-32, Rev. 4 “Indian Point Unit 2 (IP2) and Unit 3 (IP3) Refined EAF Analyses and EAF Screening Evaluations” (Oct. 2015) [PROPRIETARY]   | 11/11/2015              |                                  |
| ENT000684         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Cases of ASME Boiler and Pressure Vessel, Code Case N-779, “Alternative Rules for Simplified Elastic-Plastic Analysis, Class 1” (Section III, Division 1) (Jan. 26, 2009) [Full-Text Copyright]                            | 8/10/2015               |                                  |
| ENT00686A-C       | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Westinghouse, WESTEMS™ User Manual, Volume 2: Design Analysis, Rev. 6 (Mar. 2015) [PROPRIETARY]  | 8/10/2015               |                                  |
| ENT000687         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | NRC, Safety Evaluation Report, “Topical Report on ASME Section III Piping and Component Fatigue Analysis Utilizing the WESTEMS™ Computer Code” (WCAP-17577, Revision 2) (undated)  | 8/10/2015               |                                  |
| ENT000688         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Westinghouse, Calculation Note CN-PAFM-13-40, Rev. 1, “Indian Point Unit 2 and Unit 3 Pressurizer Spray Nozzle Transfer Function Database Development and Environmental Fatigue Evaluations” (Jan. 15, 2015) [PROPRIETARY] | 8/10/2015               |                                  |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>  | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|--|--------------------------------|---|
| ENTR00689                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Westinghouse, WCAP-12191, Rev. 5, Transient and Fatigue Cycle Monitoring Program Transient History Evaluation Report for Indian Point Unit 2 (Oct. 2015) [PROPRIETARY]                         | 11/11/2015                     |   |
| ENTR00690                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Westinghouse, WCAP-16898-P, Rev. 2, Indian Point Unit 3 Transient and Fatigue Cycle Monitoring Program Transient History Evaluation (Oct. 2015) [PROPRIETARY]                                  | 11/11/2015                     |   |
| ENT000691                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | EPRI, BWRVIP-187, BWR Vessel and Internals Project: Controlling Intergranular Stress Corrosion Cracking During a BWR Startup-Addition of Hydrazine or Carbohydrazide (Mar. 2008) [PROPRIETARY] | 8/10/2015                      |   |
| ENT000692                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Entergy, 0-CY-2310, Rev. 24, Reactor Coolant System Specification and Frequencies (Jan. 16, 2015)  | 8/10/2015                      |   |
| ENT000693                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | IPEC, Unit 3 Chemistry Data (Mar. 21-22, 2015)   | 8/10/2015                      |   |
| ENT000694                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Z. Szklarska-Smialowska et al., Mechanism of Crack Growth in Alloy 600 in High-Temperature Deaerated Water, 50 Corrosion 676 (Sept. 1994) [Full-Text Copyright]                                | 8/10/2015                      |   |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>  | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|--|--------------------------------|---|
| ENT000695                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Letter from J. Trapp, NRC, to J. Ventosa, Entergy, "Indian Point Nuclear Generating Unit 2 – NRC License Renewal Team Inspection Report 05000247/2013010" (Sept. 19, 2013)   | 8/10/2015                      |   |
| ENT000696                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Westinghouse, Calculation Note CN-SGDA-02-214, "4.7% Uprate Structural Evaluation of Primary and Secondary side Components for Indian Point Unit 2 (44F), 10% Plugging" (June 12, 2003)<br>[PROPRIETARY]   | 8/10/2015                      |   |
| ENT000697                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Entergy, Visual Examination of Reactor Vessel and Internals (VT-3), Summary No. 206913-RVVINT for IP2 (Mar. 10, 2014), and Summary No. 1-1200-VESS. INT. for IP3 (Mar. 13, 2015)   | 8/10/2015                      |   |
| ENT000698                | NYS-38/RK-TC-5                                  | Entergy's Revised Statement of Position Regarding Contention NYS-38/RK-TC-5 (Safety Commitments) (Aug. 10, 2015)   | 8/10/2015                      |   |
| ENT000699                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Revised Testimony of Entergy Witnesses Nelson F. Azevedo, Robert J. Dolansky, Alan B. Cox, Jack R. Strosnider, Timothy J. Griesbach, Barry M. Gordon, Randy G. Lott, and Mark A. Gray Regarding Contention NYS-38/RK-TC-5 (Safety Commitments) (Aug. 10, 2015) | 8/10/2015                      |   |
| ENT000700                | NYS-38/RK-TC-5                                  | State of New York, Riverkeeper, Inc., Nuclear Regulatory Commission Staff, and Entergy Nuclear Operations, Inc., Joint Stipulation Regarding State of New York Pre-Filed Testimony for Contention NYS-38/RK-TC-5 (Safety Commitments) (June 23, 2015)          | 8/10/2015                      |   |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENT000701                | NYS-38/RK-TC-5                                  | Letter from A. Burritt, NRC, to L. Coyle, Entergy, “Annual Assessment Letter for Indian Point Nuclear Generating Units 2 and 3 (Report 05000247/2014001 and 05000286/2014001)” (Mar. 4, 2015)                                       | 8/10/2015                      |   |
| ENT000703                | NYS-38/RK-TC-5                                  | NRC Inspection Manual, Inspection Procedure 71003, Post-Approval Site Inspection for License Renewal (Feb. 25, 2013)  | 8/10/2015                      |   |
| ENT000704                | NYS-38/RK-TC-5                                  | NRC Inspection Manual, Inspection Procedure 71013, Site Inspection for Plants with a Timely Renewal Application (Sept. 25, 2013)  | 8/10/2015                      |   |
| ENT000705                | NYS-38/RK-TC-5                                  | NRR Office Instruction, LIC-105, Revision 5, Managing Regulatory Commitments Made by Licensees to the NRC (Sept. 16, 2013)  | 8/10/2015                      |   |
| ENT000706                | NYS-38/RK-TC-5                                  | NRC Enforcement Manual, Rev. 9 (Sept. 9, 2013)  | 8/10/2015                      |   |
| ENT000707                | NYS-38/RK-TC-5                                  | Memorandum from S. Dingbaum, Assistant Inspector Gen. for Audits, NRC, to M. Satorius, Exec. Dir. for Operations, NRC, “Status of Recommendations: Audit of NRC’s Management of Licensee Commitments (OIG-11-A-17)” (Nov. 25, 2013) | 8/10/2015                      |   |
| ENT000708                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Entergy, Commitment Closure Verification Form, LRC # 43 (Aug. 27, 2013)   | 8/10/2015                      |   |
| ENT000709                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Entergy, Commitment Closure Verification Form, LRC # 49 (Aug. 27, 2013)   | 8/10/2015                      |   |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>   | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|---|--------------------------------|---|
| ENT000710                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Entergy, Commitment Closure Verification Form, LRC # 44 (June 19, 2013)   | 8/10/2015                      |   |
| ENT000711                | NYS-38/RK-TC-5                                  | H. Kawamura et al., Paper No. 141, The Effect of Zinc Addition to Simulated PWR Primary Water on the PWSCC Resistance, Crack Growth Rate and Surface Oxide Film Characteristics of Prefilmed Alloy 600 (Corrosion 98, 1998) [Full-Text Copyright] | 8/10/2015                      |   |
| ENT000712                | NYS-38/RK-TC-5                                  | P.L. Andresen et al., Effects of Hydrogen on Stress Corrosion Crack Growth Rate of Nickel Alloys in High-Temperature Water, 64 Corrosion 707 (Sept. 2008) [Full-Text Copyright]   | 8/10/2015                      |   |
| ENT000713                | NYS-38/RK-TC-5                                  | B. Gordon, Corrosion and Corrosion Control in Light Water Reactors, 65 Journal of Metals 1043 (Aug. 2013) [Full-Text Copyright]   | 8/10/2015                      |   |
| ENT00714A-B              | NYS-38/RK-TC-5                                  | H. Cothron et al., EPRI, Slides: NRC/Industry Meeting Regarding Tube-to-Tubesheet Weld and Divider Plate Cracking Report (July 30, 2015)  | 8/10/2015                      |   |
| ENT000715                | NYS-38/RK-TC-5                                  | NRC, Notice of Meeting with Industry on Divider Plate and Tube-to-Tubesheet Weld (July 1, 2015)   | 8/10/2015                      |   |
| ENT000716                | NYS-38/RK-TC-5                                  | EPRI, Final Report No. 3002000473, Steam Generator Channel Head Degradation Failure Modes and Effects Analysis (Apr. 2013) [Full-Text Copyright]  | 8/10/2015                      |   |
| ENT000717                | NYS-38/RK-TC-5                                  | Entergy Procedure SEP-SG-IP3-001, IP3 Steam Generator Program, Revision 1 (May 21, 2014)  | 8/10/2015                      |   |

| <b>Entergy Exhibit #</b> | <b>Track 2 Contentions Addressed by Exhibit</b> | <b>Exhibit Name</b>  | <b>Exhibit Submission Date</b> | <b>Admitted During Track 1 Hearing?</b> |
|--------------------------|---|--|--------------------------------|---|
| ENT000718                | NYS-38/RK-TC-5                                  | Westinghouse, Technical Manual No. TM 1440-C348, Vertical Steam Generator Instructions for Consolidated Edison Company of New York, Indian Point Station – Unit 2 (2001) [PROPRIETARY] (excerpt)   | 8/10/2015                      |   |
| ENT000719                | NYS-38/RK-TC-5                                  | T. Couvant et al., Paper Reference No. A004T04, PWSCC of Steam Generator Divider Plates in Alloy 600: Coupling Field Characterizations with R&D Studies (Fontevraud 7, Sept. 26-30, 2010) [Full-Text Copyright]  | 8/10/2015                      |   |
| ENT000720                | NYS-38/RK-TC-5                                  | M. Boccanfuso, et al., Paper Reference No. A165-T06, Steam Generator Mechanical Plug Failure: A Tribologic Problem (Fontevraud 7, Sept. 26-30, 2010) [Full-Text Copyright]   | 8/10/2015                      |   |
| ENT000721                | NYS-38/RK-TC-5                                  | EPRI, MRP-55, Rev. 1, Materials Reliability Program: Crack Growth Rates for Evaluating Primary Water Stress Corrosion Cracking (PWSCC) of Thick-Wall Alloy 600 Materials (Nov. 2002) [Full-Text Copyright]   | 8/10/2015                      |   |
| ENT000722                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Supplemental Testimony of Entergy Witnesses Nelson F. Azevedo, Timothy J. Griesbach, and Randy G. Lott Regarding Contention NYS-25 (Reactor Vessel Internals AMP), NYS-26B/RK-TC-1B (Metal Fatigue), and NYS-38/RK-TC-5 (Safety Commitments) (Oct. 29, 2015) | 10/29/2015                     |   |
| ENT000723                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | D.J. Gavenda et al., NUREG/CR-6428, “Effects of Thermal Aging on Fracture Toughness and Charpy-Impact Strengths of Stainless Steel Pipe Welds” (May 1996)  | 10/29/2015                     |   |
| ENT000724                | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5        | Westinghouse, Calculation Note CN-RIDA-13-48, Rev. 0 “Indian Point Units 2 and 3 Reactor Internals Lower Support Column Bodies Thermal Embrittlement and Irradiation Embrittlement Screening Assessment” (Oct. 15, 2013) [PROPRIETARY]                       | 10/29/2015                     |   |

| Entergy Exhibit # | Track 2 Contentions Addressed by Exhibit | Exhibit Name   | Exhibit Submission Date | Admitted During Track 1 Hearing? |
|-------------------|--|--|-------------------------|----------------------------------|
| ENT000725         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Westinghouse, WCAP-14574-A, License Renewal Evaluation: Aging Management Evaluation for Pressurizers (Dec. 2000)   | 10/29/2015              |                                  |
| ENTR20726         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Entergy Track 2 Hearing Exhibit List   | 3/18/2016               |                                  |
| ENT000727         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Westinghouse, Calculation Note CN-PAFM-09-21, Rev. 4, Indian Point Units 2 and 3 Charging Nozzles Environmental Fatigue Evaluation (Oct. 2015) [PROPRIETARY]   | 11/11/2015              |                                  |
| ENT000728         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Errata Sheet (noting conforming corrections to the Revised Testimony of Entergy Witnesses Nelson F. Azevedo, Alan B. Cox, Jack R. Strosnider, Randy G. Lott, Mark A. Gray, and Barry M. Gordon Regarding Contention NYS-26B/RK-TC-1B (Metal Fatigue) (Aug. 10, 2015) (ENT000679) and the Revised Testimony of Entergy Witnesses Nelson F. Azevedo, Robert J. Dolansky, Alan B. Cox, Jack R. Strosnider, Timothy J. Griesbach, Barry M. Gordon, Randy G. Lott, and Mark A. Gray Regarding Contention NYS-38/RK-TC-5 (Safety Commitments) (Aug. 10, 2015) (ENT000699) pursuant to the Atomic Safety and Licensing Board's order granting Entergy's Unopposed Motion for Leave to File New and Revised Hearing Exhibits (filed November 11, 2015)). | 11/11/2015              |                                  |

| Entergy Exhibit # | Track 2 Contentions Addressed by Exhibit | Exhibit Name   | Exhibit Submission Date | Admitted During Track 1 Hearing? |
|-------------------|--|--|-------------------------|----------------------------------|
| ENT000729         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | Testimony of Entergy Witnesses Nelson F. Azevedo, Alan B. Cox, Robert J. Dolansky, Barry M. Gordon, Timothy J. Griesbach, Randy G. Lott, and Jack R. Strosnider Regarding Additional New York State Exhibits on Contentions NYS-25 (Reactor Vessel Internals), NYS-26B/RK-TC-1B (Metal Fatigue), and NYS-38/RK-TC-5 (Safety Commitments) (Mar. 18, 2016) | 3/18/2016               |                                  |
| ENT000730         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | WCAP-17949-P, Rev. 1, “Background and Technical Basis Supporting Engineering Flaw Acceptance Criteria for Indian Point Unit 2 Reactor Vessel Internals MRP-227-A Primary and Expansion Components” (Mar. 4, 2016)  | 3/18/2016               |                                  |
| ENT000731         | NYS-25, NYS-26B/RK-TC-1B, NYS-38/RK-TC-5 | WCAP-17951-P, Rev. 1, “Background and Technical Basis Supporting Engineering Flaw Acceptance Criteria for Indian Point Unit 3 Reactor Vessel Internals MRP-227-A Primary and Expansion Components” (Mar. 4, 2016)  | 3/18/2016               |                                  |

DB1/ 85187843