

## **Saxton, John**

---

**From:** Kevin Shelburne <kevin.shelburne@UR-Energy.com>  
**Sent:** Monday, March 21, 2016 11:53 AM  
**To:** Saxton, John  
**Cc:** John Cash  
**Subject:** [External\_Sender] Responses to Class V Application Comments

John,

The following presents our responses to your March 17, 2016 request for clarification.

### **Comment 1:**

The April report lists the distance to the water supply wells as “approximately 240 feet” whereas the March report lists the distance as “approximately 200 feet”. The coordinates in Table 4-2 would suggest a distance of approximately 175 feet, but would not be consistent with distances shown on Plate 1. Can you please clarify the distance from the well to the potable water supply well?

### **Response to Comment 1:**

Our database survey coordinates for FG7 and LC1148W indicate a distance of 236.83 feet between these two wells, hence the use of “approximately 240 feet” verbiage in the April report.

The distances between the wells shown on Plate 1 were based on “estimated” coordinates before the “actual” survey coordinates were available.

### **Comment 2:**

The exploratory drill-hole map from the approved license application shows only one drill hole (D-20) in the vicinity of the proposed action. Is that correct and has the drill hole been properly abandoned?

### **Response to Comment 2:**

The coordinates for exploration drill-hole D-20 on Table 2.6-4 in the 2008 license application have since been determined to be incorrect. The actual location is 2,213 feet NNE of FG6, and was drilled by Conoco in 1973 to a depth of 620 feet. Our database provides no information on whether the drill-hole was abandoned or not. The only other exploration holes drilled in the immediate vicinity were drilled by Lost Creek, and were properly abandoned per regulation.

Regards,  
Kevin

### ***Kevin Shelburne, PG***

Senior Hydrogeologist  
Ur-Energy USA, Inc.  
5880 Enterprise Drive, Suite 200  
Casper, WY 82609  
307-265-2373 ext. 317  
Cell 775-235-3002



**Saxton, John**

---

**From:** Saxton, John  
**Sent:** Thursday, March 17, 2016 1:31 PM  
**To:** John Cash  
**Subject:** Two misc items that need clarification for the Class V

John,

I need clarification on two items –

(1)

The April report lists the distance to the water supply wells as “approximately 240 feet” whereas the March report lists the distance as “approximately 200 feet”.

The coordinates in Table 4-2 would suggest a distance of approximately 175 feet but would not be consistent with distances shown on Plate 1.

Can you please clarify the distance from well FG7 to the potable water supply well?

(2)

The exploratory drill hole map from the approved license application shows only one drill hole (D-20) in the vicinity of the proposed action. Is that correct and has the drill hole been properly abandoned?

John