

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Goldsmith Heck Engineers, Inc. P.O. Box 70 111 2 nd Street East Mobridge, South Dakota 57601 REPORT NO: 2015-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Blvd Arlington, Texas 76011-4511	
3. DOCKET NUMBER 030-34989		4. LICENSE NUMBER 40-27625-01	
5. DATE OF INSPECTION December 2 - 23, 2015			

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 20.1101(c) requires the licensee to annually review the content and implementation of the radiation protection program. During years 2013 and 2014, Goldsmith Heck Engineers, Inc. did not complete the review. Goldsmith Heck Engineers completed the review for 2015 on December 7, 2015, and intends to complete future reviews no later than December of each year by completing the Radiation Safety Program Audit contained in NUREG-1556, Volume 2.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Todd Goldsmith	<i>Todd Goldsmith</i>	11/19/16
NRC INSPECTOR	Don Stearns	<i>Donald L Stearns</i>	12/23/15
BRANCH CHIEF	Brooke G. Smith	<i>Brooke G. Smith</i>	1/20/16

Non-Public
 Sensitive -- Security-Related
 Public
 Non-Sensitive

Stearns, Don

From: Stearns, Don
Sent: Tuesday, January 19, 2016 2:52 PM
To: 'Lane Goldsmith'
Subject: Inspection Report
Attachments: Goldsmith Heck Eng.pdf

Mr. Goldsmith; attached is the inspection report from the inspection conducted December 2, 2015, at your facility. It shows one violation for failure to perform the annual program audit.

Please sign this form and email it back to me as soon as possible. If you have any questions, please feel free to call or email.

Thank You

Don Stearns
USNRC Region IV
Health Physicist
817-200-1176

Stearns, Don

From: Lane Goldsmith <goldeng@westriv.com>
Sent: Tuesday, January 19, 2016 3:44 PM
To: Stearns, Don
Subject: [External_Sender] Re: Inspection Report
Attachments: Safety Inspection.pdf

Mr. Stearns,

Attached is the signed inspection report.

Lane Goldsmith, DE
Goldsmith Heck Engineers, Inc.
PO Box 70, Mobridge SD 57601
Phone: (605) 845-3125
Fax: (605) 845-3155

----- Original Message -----

From: Stearns, Don
To: Lane Goldsmith
Sent: Tuesday, January 19, 2016 2:52 PM
Subject: Inspection Report

Mr. Goldsmith; attached is the inspection report from the inspection conducted December 2, 2015, at your facility. It shows one violation for failure to perform the annual program audit.

Please sign this form and email it back to me as soon as possible. If you have any questions, please feel free to call or email.

Thank You

Don Stearns
USNRC Region IV
Health Physicist
817-200-1176