



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION III
2443 WARRENVILLE RD. SUITE 210
LISLE, IL 60532-4352

MAR 28 2016

Akilah C. Calhoun
Radiation Safety Officer
Phillips 66 Pipeline, LLC
P.O. Box 4428
Houston, TX 77210

Dear Ms. Calhoun:

Enclosed is NRC License No. 42-15582-01, issued as the result of the mailing address change from 550-32 South Tower, 1000 South Pine, Ponca City, Oklahoma; to P.O. Box 4428, Houston, Texas, that was requested with your renewal application. We terminated License No. 35-15582-01 and issued License 42-15582-01 concurrently to prevent any interruption in your licensed activities. Also, we have voided your renewal request under the "old" license number 35-15582-01.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify the U.S. Nuclear Regulatory Commission, Region III office at (630) 829-9887 so that we can provide appropriate corrections and answers.

Please note, as we discussed by telephone on March 21, 2016, we have not added you as a gauge user at this time, because we were unable to find a copy of your gauge user training completion certificate. If find your gauge user training completion certificate, you may resubmit your request as an amendment or you may follow the training requirements specified in License Condition 11.

You will be periodically inspected by NRC. Failure to conduct your program in accordance with NRC regulations, license conditions, and representations made in your license application and supplemental correspondence with NRC will result in enforcement action against you. This could include issuance of a notice of violation, or imposition of a civil penalty, or an order suspending, modifying or revoking your license as specified in the General Statement of Policy and Procedure for NRC Enforcement Actions. Since serious consequences to employees and the public can result from failure to comply with NRC requirements, prompt and vigorous enforcement action will be taken when dealing with licensees who do not achieve the necessary meticulous attention to detail and the high standard of compliance which NRC expects of its licensees.

The NRC's Safety Culture Policy Statement became effective in June 2011. While a policy statement and not a regulation, it sets forth the agency's *expectations* for individuals and organizations to establish and maintain a positive safety culture. You can access the policy statement and supporting material that may benefit your organization on NRC's safety culture Web site at <http://www.nrc.gov/about-nrc/regulatory/enforcement/safety-culture.html>. We strongly encourage you to review this material and adapt it to your particular needs in order to develop and maintain a positive safety culture as you engage in NRC-regulated activities.

The enclosed document contains sensitive security-related information.
When separated from this cover letter this letter is uncontrolled.

A.C. Calhoun

NRC's Regulatory Issue Summary (RIS) 2005-31 provides criteria to identify security-related sensitive information and guidance for handling and marking of such documents. This ensures that potentially sensitive information is not made publicly available through NRC's Agencywide Documents Access and Management System (ADAMS), the NRC's electronic document system. Pursuant to NRC's RIS 2005-31 and in accordance with 10 CFR 2.390, the enclosed license document is exempt from public disclosure because its disclosure to unauthorized individuals could present a security vulnerability. The RIS may be located on the NRC Web site at: <http://www.nrc.gov/reading-rm/doc-collections/gen-comm/reg-issues/2005/ri200531.pdf> and the link for frequently asked questions regarding protection of security related sensitive information may be located at: <http://www.nrc.gov/reading-rm/sensitive-info/faq.html>. In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in ADAMS, accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

Sincerely,



William P. Reichhold
Materials Licensing Branch

License No. 42-15582-01
Docket No. 030-38900
Enclosure: New License 42-15582-01

The enclosed document contains sensitive security-related information.
When separated from this cover letter this letter is uncontrolled.