, ACCE	LERATED I	DISTRIBUTI	ON I	DEMONSTRATI	on sy	STEM	
	REGUL	ATORY INFORM	ATION D	ISTRIBUTION SYST	TEM (RIDS)	
ESSION NBR:8809220178 DOC.DATE: 88/09/08 NOTARIZED: NO DOCKET # CIL:50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287 AUTH.NAME AUTHOR AFFILIATION HERDT,A.R. Region 2, Ofc of the Director RECIP.NAME RECIPIENT AFFILIATION TUCKER,H.B. Duke Power Co.							
SUBJECT: Forwards Insp Repts 50-269/88-23,50-270/88-23 & 50-287/88-23 on 880801-05.No violations noted.							
DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR $\frac{1}{2}$ ENCL $\frac{1}{2}$ SIZE: $\frac{2+10}{D}$ D TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response D							
	EOD/Ornstein: EOD/Ornstein: EOD/Ornstein:	lcy.				05000269 05000270 05000287)
	RECIPIENT	COPIE	5	RECIPIENT	COPI	ES	A
÷.	ID CODE/NAI PD2-3 PD	ME LTTR 1 1		ID CODE/NAME PASTIS,H	LTTR 1 2		D
INTERNAL:		2		AEOD	1	1	D
	DEDRO NRR/DLPQ/PEB NRR/DOEA DIR	1 11 1 11 1	1 1	NRR MORISSEAU,D NRR/DLPQ/QAB 10 NRR/DREP/EPB 10	1 1 1	1 1 1	S
	NRR/DREP/RPB NRR/PMAS/ILR OE_LIEBERMAN REG_FILE RGN2 FILE	10 2 B12 1	2 h 1 h 1 c	NRR/DRIS DIR 9A NUDOCS-ABSTRACT OGC/HDS2 RES/DSIR DEPY	1 1 1 1	1 1 1 1	
EXTERNAL:	LPDR NSIC	1	1 h 1	IRC PDR	1	1	-
NOTES:		1	. 1			. · · · .	

R

I

D

S

A

D

D

S

TOTAL NUMBER OF COPIES REQUIRED: LTTR 26 ENCL 26

SEP 08 1988

Y ellow

Docket Nos. 50-269, 50-270, 50-287 License Nos. DPR-38, DPR-47, DPR-55

Duke Power Company ATTN: Mr. H. B. Tucker, Vice President Nuclear Production Department 422 South Church Street Charlotte, NC 28242

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-269/88-23, 50-270/88-23 AND 50-287/88-23

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by Rich C. Chou on August 1-5, 1988. The inspection included a review of activities authorized for your Oconee facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

Your attention is invited to the unresolved items identified in the inspection report. These matters will be pursued during future inspections.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely.

Alan R. Herdt, Chief Engineering Branch Division of Reactor Safety

TEOI

Enclosure: NRC Inspection Report

cc w/encl: M. S. Tuckman, Station Manager

> 3809220178 380908 PDR ADOCK 05000269



bcc: (See page 2) •

SEP 08 1988

Duke Power Company

2

bcc w/encl: NRC Resident Inspector DRS Technical Assistant H. Pastis, NRR Document Control Desk State of South Carolina

RII RCChou:es 8/2/88

Blake Ø /88

7/88