DISTRIBUTION DEMONSTRATION CELERATED

SYSTEM

R

I

D

S

D

D

S

	· · · · · · · · · · · · · · · · · · ·		•		
REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)					
FACIL:5	.L. Region 2, NAME RECIPIEN	r Station, U r Station, U r Station, U FFILIATION Ofc of the F AFFILIATIO	nit 1, Duke Power (nit 2, Duke Power (nit 3, Duke Power (Director	Co.	DOCKET # 05000269 05000270 05000287 R
SUBJECT: Forwards Insp Repts 50-269/89-03,50-270/89-03 & 50-287/89-03 I on 890104-13.No violations or deviations noted. DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR L ENCL SIZE: 2+59 S TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response S					
NOTES:				· · ·	
	RECIPIENT ID CODE/NAME PD2-3 PD	COPIES LTTR ENCL 1 1	RECIPIENT ID CODE/NAME PASTIS,H	COPIES LTTR ENCL 1 1	A D
INTERNAL:	ACRS AEOD/DEIIB NRR SHANKMAN,S NRR/DLPQ/PEB 11 NRR/DOEA DIR 11 NRR/DREP/RPB 10 NRR/PMAS/ILRB12 OE_LIEBERMAN,J REG FILE 02	2 2 1 1 1 1 1 1 1 1 2 2 1 1 1 1	AEOD DEDRO NRR/DEST DIR NRR/DLPQ/QAB 10 NRR/DREP/EPB 10 NRR/DRIS DIR 9A NUDOCS-ABSTRACT OGC/HDS2 RGN2 FILE 01	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	D S
EXTERNAL:	LPDR NSIC	1 1 1 1	NRC PDR	1 1	

NOTE TO ALL "RIDS" RECIPIENTS:



۶

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25

official

FEB 10 1989

Docket Nos. 50-269, 50-270, 50-287 License Nos. DPR-38, DPR-47, DPR-55

Duke Power Company ATTN: Mr. H. B. Tucker, Vice President Nuclear Production Department 422 South Church Street Charlotte, NC 28242

> 8902270195 PDR ADDCK 89021 ADDCK 85000

Gentlemen:

SUBJECT: INSPECTION REPORT NOS. 50-269/89-03, 50-270/89-03 AND 50-287/89-03

This refers to the NRC inspection conducted by an Augmented Inspection Team (AIT) on January 4 - 13, 1989. The inspection included a review of activities authorized for your Oconee facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, and interviews with personnel.

Within the scope of the inspection, no violations or deviations were identified.

Your attention is invited to the unresolved items identified in the inspection report. These matters will be pursued during future inspections.

The AIT found that your plant's staff and management actions were appropriate during the recovery from the reactor trip of January 2 and the plant recovery from the fire of January 3. There are several items which remain to be resolved and are highlighted in the report.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room. Duke Power Company



Should you have any questions concerning this letter, please contact us.


Sincerely,

Malcolm L. Ernst Acting Regional Administrator

Enclosure: Inspection Report

cc w/encl: M. S. Tuckman, Station Manager State of South Carolina

bcc w/encl: NRC Resident Inspector DRS Technical Assistant H. Pastis, NRR Document Control Desk



/89

bles. 2/ : /89

Reyes 6/89



GJen kins 2/1/89

