

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

December 7, 1979

TELEPHONE: AREA 704
373-4083


Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303

Re: Oconee 3
Docket Number 50-287

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-287/79-12. This report is submitted pursuant to Oconee Nuclear Station Technical Specification 6.6.2.1.b(2), which concerns operation in a degraded mode permitted by a limiting condition for operation, and describes an incident which is considered to have no significance with respect to its effect on the health and safety of the public.

Very truly yours,



William O. Parker, Jr.

SRL/sch
Attachment

cc: Director, Office of Management Information
and Program Control



Apr 5 11
~~7912110126~~

7912110 362

Mr. James P. O'Reilly, Director
December 20, 1979
Page Two

system to service. Double verification is now required in order to assure proper alignment. The personnel responsible for the spill have been disciplined, and all operating personnel have been counseled. These actions are considered to provide adequate assurance against a recurrence of a similar incident.

Very truly yours,

William O. Parker Jr.

William O. Parker, Jr.

W O A H

SRL/sch