

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9210140159 DOC. DATE: 92/10/06 NOTARIZED: NO DOCKET #
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287

AUTH. NAME AUTHOR AFFILIATION
 HAMPTON, J.W. Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Revised response to violations noted in insp repts
 50-269/91-35, 50-270/91-35 & 50-287/91-35 submitted on
 920227. Some improvements were made to unit 3, addl review &
 modifications planned.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME		LTR	ENCL		
	PD2-3 PD	1	1	WIENS, L	1	1			
INTERNAL:	ACRS	2	2	AEOD	1	1			
	AEOD/DEIB	2	2	AEOD/DSP/TPAB	1	1			
	AEOD/TTC	1	1	DEDRO	1	1			
	NRR MORISSEAU, D	1	1	NRR/DLPQ/LHFBPT	1	1			
	NRR/DLPQ/LPEB10	1	1	NRR/DOEA/OEAB	1	1			
	NRR/DREP/PEPB9H	1	1	NRR/PMAS/ILRB12	1	1			
	NUDOCS-ABSTRACT	1	1	OE DIR	1	1			
	OGC/HDS2	1	1	<u>REG FILE</u> 02	1	1			
	RGN2 FILE 01	1	1						
EXTERNAL:	EG&G/BRYCE, J.H.	1	1	NRC PDR	1	1			
	NSIC	1	1						

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 24 ENCL 24

R
I
D
S
/
A
D
S
/
A
D
S

Duke Power Company
Oconee Nuclear Generation Department
P.O. Box 1439
Seneca, SC 29679

J.W. HAMPTON
Vice President
(803)885-3499 Office
(704)373-5222 FAX



DUKE POWER

October 6, 1992

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: Oconee Nuclear Station
Docket Nos. 50-287
Inspection Report 50-269, -270, -287/91-35
Reply to Notice of Violation - Revision

Dear Sir:

By letter dated January 14, 1992, the NRC issued Inspection Report No. 50-269, -270, -287/91-35 with a Notice of Violation. Pursuant to the provision of 10 CFR 2.201, a written response to the violation identified in the above inspection report was submitted on February 27, 1992.

Within the violation response, Oconee committed to revise the controlling procedures for startup and shutdown to improve the control of the valve alignments for systems used to provide Reactor Building outage service functions, such as Instrument Air. This action was committed to be completed prior to each unit's next refueling outage shutdown.

This letter is to advise you that although some improvements were made to the Unit 3 shutdown procedure prior to the EOC 13 refueling outage, additional review and procedure modifications are planned associated with a Unit 1 valve mispositioning event which will affect the control of containment isolation valves. These changes will be described in LER 269/92-13 and will be in place prior to the next Unit 3 refueling outage (EOC 14). The original commitment schedule for Units 1 and 2 remain unchanged.

Should you have further questions, please feel free to contact M.E. Patrick at (803) 885-3292.

Very truly yours,

J.W. Hampton
J. W. Hampton
Vice President

100006
9210140159 921006
PDR ADCK 05000269
PDR

IEO1
/10 (Poor Original)

Document Control Desk
October 6, 1992
Page 2

OCK/ock

xc:

Mr. S. D. Ebnetter, Regional Administrator
US Nuclear Regulatory Commission, Region II
101 Marietta Street, NW Suite 2900
Atlanta, GA 30323

Mr. L. A. Wiens, Project Manager
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
One White Flint North, Mail Stop 9H3
Washington, DC 20555

Mr. P. E. Harmon
NRC Senior Resident Inspector
Oconee Nuclear Site