

# ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9302250255      DOC. DATE: 93/02/18      NOTARIZED: NO  
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.  
 AUTH. NAME:                      AUTHOR AFFILIATION  
 HAMPTON, J.W.                  Duke Power Co.  
 RECIPIENT NAME:                RECIPIENT AFFILIATION  
    Document Control Branch (Document Control Desk)

DOCKET #  
05000269

SUBJECT: Requests that LER 50-269/92-20 re inadequate cooling water flow to turbine-driven emergency feedwater pump oil cooler which may occur during station blackout be rescinded. Further testing indicated pump would operate as required during SBO.

DISTRIBUTION CODE: IE22D      COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES		
	ID CODE/NAME	LTR	ENCL		
	PD2-3 LA	1	1		
	WIENS, L	1	1		
INTERNAL:	ACNW	2	2		
	AEOD/DOA	1	1		
	AEOD/ROAB/DSP	2	2		
	NRR/DLPQ/LHFB10	1	1		
	NRR/DRCH/HICB8H	1	1		
	NRR/DRSS/PRPB11	2	2		
	NRR/DSSA/SRXB8E	1	1		
	REG FILE 02	1	1		
	RGN2 FILE 01	1	1		
EXTERNAL:	EG&G BRYCE, J.H	2	2		
	NRC PDR	1	1		
	NSIC POORE, W.	1	1		
	PD2-3 PD	1	1		
	ACRS	2	2		
	AEOD/DSP/TPAB	1	1		
	NRR/DE/EMEB 7E	1	1		
	NRR/DOEA/OEAB	1	1		
	NRR/DRIL/RPEB10	1	1		
	NRR/DSSA/SPLB8D	1	1		
	NRR/DST/SELB 8D	1	1		
	RES/DSIR/EIB	1	1		
	L ST LOBBY WARD	1	1		
	NSIC MURPHY, G.A	1	1		
	NUDOCS FULL TXT	1	1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 31 ENCL 31

Duke Power Company  
Oconee Nuclear Generation Department  
P.O. Box 1439  
Seneca, SC 29679

J.W. HAMPTON  
Vice President  
(803)885-3499 Office  
(704)373-5222 FAX



**DUKE POWER**

February 18, 1993

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Subject: Oconee Nuclear Site  
Docket Nos. 50-269, -270, -287  
LER 269/92-20

Gentleman:

Licensee Event Report 269/92-20, "Inadequate Cooling Water Flow To The Turbine Driven Emergency Feedwater Pump Oil Cooler May Occur During A Station Blackout", was submitted on January 20, 1993. Corrective actions were taken on all three units to ensure that adequate cooling water flow would be available to the oil cooler during a Station Blackout. Further testing indicated that the Turbine Driven Emergency Feedwater would operate as required during a Station Blackout without cooling water and the Licensee Event Report is not required.

A test was performed on February 4, 1993 to determine if the Turbine Driven Emergency Feedwater Pump can operate for four hours with the cooling water supply to the turbine oil cooler isolated without exceeding temperature limits specified by the manufacturer, General Electric. The Turbine Driven Emergency Feedwater Pump operated for four hours and eight minutes, during the test no temperatures specified by the manufacturer were exceeded. Based on the test results and Calculation #OSC-5258, the operability determination declares the pump to be past operable.

In light of this information, Duke Power Company has determined the event not reportable per 10 CFR 50.73 (a)(2)(B) and would like to rescind Licensee Event Report 269/92-20.

Very truly yours,

*Joe M Davis*  
for J. W. Hampton  
Vice President

9302250255 930218  
PDR ADOCK 05000269  
S PDR

*TELL*  
*'10*

February 18, 1993

Page 2

xc: Mr. S. D. Ebnetter  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta St., NW, Suite 2900  
Atlanta, Georgia 30323

Mr. L. A. Wiens  
Office of Nuclear Regulation  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

Mr. P. E. Harmon  
NRC Resident Inspector  
Oconee Nuclear Site