

CATEGORY 1

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9708080047 DOC. DATE: 97/07/31 NOTARIZED: NO
FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.
AUTH. NAME AUTHOR AFFILIATION
MCCOLLUM, W.R. Duke Power Co.
RECIP. NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

DOCKET #
05000269

SUBJECT: Forwards LER 97-002-01 re reactor bldg cooling units that were declared inoperable due to design deficiency, IAW 10CFR50.73(a)(2)(V)(D).

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+7
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

| | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL |
|-----------|---------------------------|---------------------|---------------------------|---------------------|
| | PD2-2 PD | 1 1 | LABARGE, D | 1 1 |
| INTERNAL: | ACRS | 1 1 | AEOD/SPD/RAB | 2 2 |
| | AEOD/SPD/RRAB | 1 1 | <u>FILE CENTER</u> | 1 1 |
| | NRR/DE/ECGB | 1 1 | NRR/DE/EELB | 1 1 |
| | NRR/DE/EMEB | 1 1 | NRR/DRCH/HHFB | 1 1 |
| | NRR/DRCH/HICB | 1 1 | NRR/DRCH/HOLB | 1 1 |
| | NRR/DRCH/HQMB | 1 1 | NRR/DRPM/PECB | 1 1 |
| | NRR/DSSA/SPLB | 1 1 | NRR/DSSA/SRXB | 1 1 |
| | RES/DET/EIB | 1 1 | RGN2 FILE 01 | 1 1 |
| EXTERNAL: | L ST LOBBY WARD | 1 1 | LITCO BRYCE, J H | 1 1 |
| | NOAC POORE, W. | 1 1 | NOAC QUEENER, DS | 1 1 |
| | NRC PDR | 1 1 | NUDOCS FULL TXT | 1 1 |

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
ROOM OWFN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM
DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25

C
A
T
E
G
O
R
Y
1
D
O
C
U
M
E
N
T



Duke Power Company

A Duke Energy Company

Oconee Nuclear Site

P.O. Box 1439

Seneca, SC 29679

W. R. McCollum, Jr.
Vice President

(864) 885-3107 OFFICE

(864) 885-3564 FAX

July 31, 1997

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287
Licensee Event Report 269/97-02, Revision 01
Problem Investigation Process No.: 2-097-0240

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report, 269/97-02, concerning "Reactor Building Cooling Units Technically Inoperable Due To Design Deficiency".

This is a supplemental report to include pertinent information related to the event. The original report contained only the Abstract. This entire supplement should be considered revised or supplementary information. It is being submitted in accordance with 10 CFR 50.73 (a) (2) (V) (D). This event is considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

W. R. McCollum, Jr.

Attachment

070040



9708080047 970731
PDR ADOCK 05000269
S PDR

111
Jerr

Document Control Desk
July 31, 1997
Page 2

xc:

Mr. Luis A. Reyes
Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

Mr. D. E. LaBarge
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957

Mr. M. A. Scott
NRC Resident Inspector
Oconee Nuclear Station