

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9405310154 DOC. DATE: 94/05/24 NOTARIZED: NO DOCKET #
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270

AUTH. NAME AUTHOR AFFILIATION
 HAMPTON, J.W. Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Corrects listed statement in 940517 request for relief 93-11 stating util will perform volumetric exam of 25% of welds within sys boundary covered by request, rather than 10 welds.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code - GL-89-04

NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	PD2-3 LA	1	0	PD2-3 PD	1	1
	WIENS, L	2	2			
INTERNAL:	ACRS	6	0	AEOD/DSP/ROAB	1	1
	NRR/DE/EMEB	1	1	NRR/EMCB	1	1
	NUDOCS-ABSTRACT	1	1	OC/LEDCEB	1	0
	OGC/HDS2	1	0	<u>REG FILE</u> 01	1	1
	RES/DSIR/EIB	1	1			
EXTERNAL:	EG&G BROWN, B	1	1	EG&G RANSOME, C	1	1
	NRC PDR	1	1	NSIC	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 22 ENCL ~~10~~ 0

R
I
D
S
/
A
D
D
S

 R
I
D
S
/
A
D
D
S

Duke Power Company
Oconee Nuclear Site
P.O. Box 1439
Seneca, SC 29679

J. W. HAMPTON
Vice President
(803)885-3499 Office
(803)885-3564 Fax



DUKE POWER

May 24, 1994

U.S. Nuclear Regulatory Commission
Attention Document Control Desk
Washington, DC 20555

Subject: Duke Power Company
Oconee Nuclear Station
Docket No. 50-269, -270
Second Ten Year Inservice Inspection Interval
Request for Relief No. 93-11
Supplementary Information

On May 17, 1994, 1993 Duke Power Company submitted Relief from Code Request 93-11. In addition to the alternate examinations specified in that submittal Duke proposed "to perform a Volumetric Examination on 10 of the welds within the system boundary covered by that request". This statement should be corrected to state "to perform a Volumetric Examination on 25 % of the welds within the system boundary covered by that request." This was an oversight in that Duke sought to apply this statement generically when in fact the number of applicable weld joints is not the same for each unit.

If there are any questions or further information is needed you may contact D. A. Nix at (803) 885-3634.

Very truly yours,

J. W. Hampton
Site Vice President

310064

9405310154 940524
PDR ADOCK 05000269
Q PDR

A047
1/0

U. S. Nuclear Regulatory Commission
Page 2

xc :

Mr. L. A. Wiens
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. S. D. Ebnetter
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission

Mr. P. E. Harmon
Senior NRC Resident Inspector
Oconee Nuclear Station

Mr. Virgil R. Autry
Bureau of Radiological Health
SC Dept. of Health & Environmental Control
2600 Bull St.
Columbia, SC 29201