

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

79 APR 16
April 13, 1979 P 2: 45

TELEPHONE: AREA 704
373-4083


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: Oconee Unit 1
Docket No. 50-269

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-269/79-10 was to have been submitted by April 13, 1979. This report describes an incident which involved the removal of a high pressure service water pump from service as a result of leakage from its motor cooler, and is considered to be of no significance with respect to safe operation of the unit. The motor cooler has been repaired, and the pump has been returned to service, but the investigation into the cause of the leakage has not been completed. It is anticipated that the investigation will be completed and the report transmitted to your office by April 27, 1979.

Very truly yours,



William O. Parker, Jr.

SRL:scs

7905140373



A002
S/O
790162
OFFICIAL

5