

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7907240290 DOC. DATE: 79/07/18 NOTARIZED: NO
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.
 AUTH. NAME: PARKER, W.O. AUTHOR AFFILIATION: Duke Power Co.
 RECIP. NAME: O'REILLY, J.P. RECIPIENT AFFILIATION: Region 2, Atlanta, Office of the Director

DOCKET #
05000269

SUBJECT: Notifies two potentially malfunctioning valves noted in RD 269/78-27 were examined 790629 & found in proper working condition, but due to mods, valves are no longer in use.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: INCIDENT REPORTS

NOTES: M. CUNNINGHAM - ALL AMENDS TO FSAR & CHANGES TO TECH SPECS.

| ACTION: | RECIPIENT ID CODE/NAME | COPIES | | RECIPIENT ID CODE/NAME | COPIES | |
|-----------|------------------------|--------|------|------------------------|--------|------|
| | | LTR | ENCL | | LTR | ENCL |
| | 05 BC <u>ORB #4</u> | 4 | 4 | | | |
| INTERNAL: | 01 <u>REG FILE</u> | 1 | 1 | 02 NRC PDR | 1 | 1 |
| | 09 I&E | 2 | 2 | 11 MPA | 3 | 3 |
| | 14 TA/EDO | 1 | 1 | 15 NOVAK/KNIEL | 1 | 1 |
| | 16 EEB | 1 | 1 | 17 AD FOR ENGR | 1 | 1 |
| | 18 PLANT SYS BR | 1 | 1 | 19 I&C SYS BR | 1 | 1 |
| | 20 AD PLANT SYS | 1 | 1 | 21 AD SYS/PROJ | 1 | 1 |
| | 22 REAC SAFT BR | 1 | 1 | 23 ENGR BR | 1 | 1 |
| | 24 KREGER | 1 | 1 | 25 PWR SYS BR | 1 | 1 |
| | 26 AD/SITE ANAL | 1 | 1 | 27 OPERA LIC BR | 1 | 1 |
| | 28 ACIDENT ANLYS | 1 | 1 | 29 AUX SYS BR | 1 | 1 |
| | E JORDAN/IE | 1 | 1 | HANAUER, S. | 1 | 1 |
| | TMI-H STREET | 1 | 1 | | | |
| EXTERNAL: | 03 LPDR | 1 | 1 | 04 NSIC | 1 | 1 |
| | 29 ACRS | 16 | 16 | | | |

JUL 25 1979

ao4
ccp

TOTAL NUMBER OF COPIES REQUIRED: LTR 48 ENCL 0

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 18, 1979

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303

REGULATORY DOCKET FILE COPY

Re: Oconee Unit 1
Docket No. 50-269

Dear Mr. O'Reilly:

My letter of January 15, 1979, transmitted to your office Reportable Occurrence Report RO-269/78-27. In the section entitled "Corrective Actions," it was noted that two potentially malfunctioning valves, valves FDW-47 and -48, would be examined at a later outage. On June 29, 1979, the two valves were examined, and it was determined that they were in proper working condition. It should be noted that since that time, operation of the emergency feed-water system has been modified such that these valves are no longer in use.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr. *by [signature]*

SRL/sch

cc: Director, Office of Management Information
and Program Control



*A002
S/P
1/10*

7907240 290 *5*