

Central Files

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

June 19, 1979

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

9 JUN 25 A10:08


REPRO PRO

Re: RII:JPO
50-269
50-270
50-287

Dear Mr. O'Reilly:

My letter of June 12, 1979 provided responses to the concerns raised by IE Bulletin 79-01 for Oconee Nuclear Station. Section III of that response addressed corrective actions required for various components for which complete documentation was not readily available. Paragraphs II, III, and IV included scheduling information for the proposed actions which indicated that those related to Unit 3 were complete. The purpose of this letter is to clarify that these statements of completion were in the context of the current refueling outage on Oconee 3. That is, the modifications will be completed prior to the return of the unit to power operation, which is anticipated in the near future.

Very truly yours,


William O. Parker, Jr.

KRW:scs

cc: NRC, Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, D. C. 20555

202
CEP

Director, Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

790303
OFFICIAL COPY

7908090038