



# SAFEGUARDS INFORMATION

UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION II

101 MARIETTA STREET, N.W.  
ATLANTA, GEORGIA 30323

JAN 11 1988

Report Nos. 50-413 and 50-414/87-43, 50-369 and 50-370/87-45, 50-269, 50-270  
and 50-287/87-50

Licensee: Duke Power Company  
Nuclear Production Department  
422 South Church Street  
Charlotte, NC 28242

Docket Nos. 50-413 and 50-414, 50-369  
and 50-370, 50-269, 50-270  
and 50-287

License Nos. NPF-35,  
NPF-52, NPF-9, NPF-17,  
DPR-38, DPR-47, DPR-55

Facility Name: Corporate Nuclear Security Department

Inspection Conducted: December 8-9, 1987

Inspector: William J. Robin  
William J. Robin, Senior Security Inspector

1/4/88  
Date Signed

Approved by: D. R. McGuire  
D. R. McGuire, Chief, Physical Security Section  
Nuclear Materials Safety and Safeguards Branch  
Division of Radiation Safety and Safeguards

1/4/88  
Date Signed

## SUMMARY

Scope: This reactive inspection was conducted at the Duke Nuclear Security Department in response to the licensee notifying the NRC that it had discovered a potential compromise of Safeguards Information.

Results: As of the date for issuance of this report, the results of this inspection were still being evaluated by NRC.

BB01140363 BB0111  
PDR ADCK 05000269  
Q PDR

ENCLOSURE CONTAINS  
SAFEGUARDS INFORMATION  
UPON SEPARATION THIS  
PAGE IS RECONTROLLED.

# SAFEGUARDS INFORMATION