

Central Filer

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

August 30, 1979

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083

79 SEP 5 11:23

USNRC REGION II
ATLANTA, GEORGIA

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: RII: IPO
50-269
50-270
50-287

Dear Mr. O'Reilly:

Please find attached Duke Power Company's responses to the concerns raised in Item 1 of IE Bulletin 79-17 as required by Item 5. The responses include the pre-service inspections, inservice inspections and a summary of the water chemistry control program for those stagnant systems potentially affected by intergranular stress corrosion cracking.

This response was due on August 24, 1979 but due to unanticipated administrative problems in copying the rather large amount of information requested the submittal was delayed to the above date.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr. *By [Signature]*

KRW:scs
Attachment

cc: Director, Division of Operating Reactors
Office of Inspection and Enforcement
Washington, D. C. 20555

790479
ORIGINAL COPY KB

7909280674

202