

*Central File*

*50-269  
270  
287*

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

November 6, 1979

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

*NOV 9 1979  
21*

Re: RII:JPO  
50-269  
50-270  
50-287

Dear Mr. O'Reilly:

My letter dated September 24, 1979 provided Duke Power Company's response to IE Bulletin 79-19 and incorrectly indicated the specification of the shipping containers used in response to Item 4. Reconditioned fifty-five gallon drums are used to meet the strong tight container requirements.

Very truly yours,

*William O. Parker, Jr.*  
William O. Parker, Jr.

RLG:scs

cc: Office of Inspection and Enforcement  
Division of Fuel Facility and Materials  
Safety Inspection  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

*AOI  
2  
CCP*

*7911280 294*

*790635*  
OFFICIAL COPY