

Central File
50-269
270
287

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

October 29, 1979

TELEPHONE: AREA 704
373-4063

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287

70
11
20

Dear Mr. O'Reilly:

Please find attached Revision 2 to Duke Power Company's response to IE Bulletin 79-02. The changes incorporated in this revision were requested by members of your staff in a discussion held on October 9, 1979 at your offices. Also attached are three additional items related to IE Bulletin 79-02 work. They are:

- Attachment 1 - TR-3501-1, Revision 1 - Summary Report, Generic Response to U.S. NRC I&E Bulletin 79-02, Base Plate/Concrete Expansion Anchor Bolts ("Teledyne Report," dated August 30, 1979)
- Attachment 2 - Duke Power Company hand calculation technique procedure as revised through October 18, 1979
- Attachment 3) - Summary of Anchor Bolt Deficiencies

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr. *By [Signature]*

KRW:scs
Attachments

AOTI
2
7912170210

11/28/83
KM
OFFICIAL COPY