

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

March 28, 1980

TELEPHONE: AREA 704
373-4083


Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303

Re: Oconee 1
Docket No. 50-269

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-269/80-5. This report describes an incident which involved a Reactor Protective System instrument setting which was less conservative than permitted, but which would not have prevented fulfillment of the functional requirements of the system, and is submitted pursuant to Oconee Nuclear Station Technical Specification 6.6.2.1.b(1), although it was of no significance with respect to safe operation, and the health and safety of the public were not affected.

Very truly yours,


William O. Parker, Jr.

SRL/sch
Attachment

cc: Director, Office of Management and
Program Analysis

Mr. Bill Lavalee
Nuclear Safety Analysis Center

A002
S
1/1

S

8004070 327