

*Central File*  
50-269  
270  
287

DUKE POWER COMPANY  
POWER BUILDING  
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

June 24, 1980, 1 A 8: 59

TELEPHONE: AREA 704  
373-4083


Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: RII:JPO  
50-269  
50-270  
50-287  
IE Bulletin 79-03A

Dear Sir:


Pursuant to your letter of April 4, 1980, which transmitted the subject bulletin, Duke Power Company has completed the actions required by Items 1 and 2. Based on a review of the original piping specifications for Oconee, no Type 300 series fusion welded piping is in use for pressure piping. Some small amount was used in floor drains only. Before such piping will be used in future application it will be reviewed by our Design Engineering Department in light of the concerns raised by this bulletin. No further action is anticipated with regard to this bulletin.

Very truly yours,

  
William O. Parker, Jr.

KRW:scs

cc: Office of Inspection and Enforcement  
Division of Reactor Construction and Inspection  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555



8007180533

OFFICIAL COPY