

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8010210551 DOC. DATE: 80/10/16 NOTARIZED: NO  
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.  
 AUTH. NAME: PARKER, W.O. AUTHOR AFFILIATION: Duke Power Co.  
 RECIP. NAME: O'REILLY, J.P. RECIPIENT AFFILIATION: Region 2, Atlanta, Office of the Director

DOCKET # 05000269

SUBJECT: Informs that LER 80-031 will be submitted by 801030 following investigation.

DISTRIBUTION CODE: M007S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2  
 TITLE: LER (Backfit)

NOTES: M Cunningham: all amends to FSAR & changes to Tech Specs. 05000269  
 AEOD, Ornstein: 1cc.

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
INTERNAL:	AEOD	2 2	ASLBP/J.HARD	1 1
	I&E 04	2 2	MPA	1 1
	NRC PDR 02	1 1	OP EX EVAL BR	1 1
	<u>REG FILE</u> 01	1 1		
EXTERNAL:	LPDR 03	1 1	NSIC	1 1

*D*

OCT 22 1980

*V*

TOTAL NUMBER OF COPIES REQUIRED: LTR 12 ENCL 12

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

October 16, 1980

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: Oconee Unit 1  
Docket No. 50-269

Dear Mr. O'Reilly:

On October 2, 1980, your office was informed of an incident which involved the incorrect resetting of the RPS flux/flow imbalance trip setpoint. Reportable Occurrence Report RO-269/80-31, providing details of the incident, was to have been submitted by October 16, 1980. However, investigation of the incident is not complete. It is expected that the report will be submitted no later than October 30, 1980.

Very truly yours,

*William O. Parker Jr.*  
William O. Parker, Jr. *by WAH*

FTP:scs

M007  
3/11

5 8010210551

