

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

RECEIVED DISTRIBUTION
SERVICES UNIT

1980 NOV 17 AM 11 01

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

November 13, 1980

TELEPHONE: AREA 704
373-4083

US NRC
DISTRIBUTION SERVICES
BRANCH

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Re: Oconee Nuclear Station
Docket No. 50-269

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-269/80-31. This report is submitted pursuant to Oconee Nuclear Station Technical Specification 6.6.2.1.a(2), which concerns operation in a mode which is less conservative than the least conservative aspect of a LCO, and describes an incident which is considered to be of no significance with respect to its effect on the health and safety of the public.

My letters of October 16, 1980 and October 30, 1980, addressed the delay in the preparation of this report.

Very truly yours,


William O. Parker, Jr. 

JLJ:scs
Attachment

cc: Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
P. O. Box 10412
Palo Alto, California 94303

A002
5/11

8011180585