

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

December 23, 1980

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: Oconee Nuclear Station  
Docket No. 50-269

RECEIVED DISTRIBUTION  
SERVICES DIVISION  
1980 DEC 29 PM 1 43  
U.S. NRC  
DISTRIBUTION SERVICES  
BRANCH

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-269/80-34. This report is submitted pursuant to Oconee Nuclear Station Technical Specification 6.6.2.1.b(2), which concerns operation in a degraded mode permitted by a limiting condition for operation, and describes an incident which is considered to be of no significance with respect to its effect on the health and safety of the public.

Very truly yours,

*William O Parker Jr WAH*  
William O. Parker, Jr.

JLJ:scs  
Attachment

cc: Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
P. O. Box 10412  
Palo Alto, California 94303

*A002  
5/11*

8012300495

5