

A002

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 05000270 OCONEE 2
RECIPIENT: O'REILLY, J.P.
ORIGINATOR: PARKER, W.O.
COMPANY NAME: DUKE PWR
SUBJECT:

DOC DATE: 781101
ACCESSION NBR: 7811080137
COPIES RECEIVED:
LTR 1 ENCL 1
SIZE: 1+3

LER#78-010/03L-0 on 781004: control rod 7 group 6 discerned to be inoper due to short in CRD stator. Short caused by moisture-induced corrosion. Will replace shorted stator during upcoming refueling outage.

DISTRIBUTION CODE: A002
DISTRIBUTION TITLE:
INCIDENT REPORTS

NOTARIZED _____

NAME	ENCL?
BR CHIEF	W/4 ENCL
REG FILE	W/ENCL
NRC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
E. Jordan	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB#4 BC

NOV 9 1978

TOTAL NUMBER OF COPIES REQUIRED:
LTR
ENCL

42
42

NOTES: M CUNNINGHAM-ALL AMDTS TO FSAR & CHANGES TO TECH SPECS.

A104
CCP

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

November 1, 1978

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

RE: Oconee Unit 2
Docket No. 50-270

Dear Mr. O'Reilly:

Pursuant to Sections 6.2 and 6.6.2 of Oconee Nuclear Station Technical Specifications, please find attached Reportable Occurrence Report RO-270/78-10.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr. *By [Signature]*

DJV:scs
Attachments

cc: Director, Office of Management Information
and Program Control

REGISTRATION BOARD FILE 60

781108 0137

A002
S
1/1