

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7908020428 DOC. DATE: 79/07/04 NOTARIZED: NO  
 FACIL: 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co.  
 AUTH. NAME AUTHOR AFFILIATION  
 \* Duke Power Co.  
 RECIPIENT NAME RECIPIENT AFFILIATION  
 JAPE, F. Region 2, Atlanta, Office of the Director

DOCKET #  
05000270

SUBJECT: RO-270/79-05 on 790630: condenser cooling water emergency discharge valves found locked closed. Caused by either personnel error or procedural problem. Valves opened.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR ( ENCL 0 SIZE: !  
 TITLE: INCIDENT REPORTS

NOTES: M CUNNINGHAM - All ADITS TO FSAR + CHANGES TO TECH SPECS.

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL
	05 BC ORB 4	4	4			
INTERNAL:	<del>01 REG FILE</del>	1	1	02 NRC PDR	1	1
	<del>09 I&amp;E</del>	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 KREGER	1	1	25 PWR SYS BR	1	1
	26 AD/SITE ANAL	1	1	27 OPERA LIC BR	1	1
	28 ACCIDENT ANLYS	1	1	29 AUX SYS BR	1	1
	E JORDAN/IE	1	1	HANAUER, S.	1	1
	TMI-H STREET	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

AUG 3 1979

ADY  
CYP

TOTAL NUMBER OF COPIES REQUIRED: LTTR 48 ENCL 48

TO: Frank Tape

USNRC REGION  
ATLANTA, GEORGIA

IE MAIL  
FILE: R-869 J. P. O'NEILL

OCONEE NRC/OTR PRINCIPAL INSPECTOR

79 JUL 5 A 8: 22

DUKE POWER COMPANY  
OCONEE NUCLEAR STATION  
NRC NOTIFICATION OF REPORTABLE OCCURRENCE

C. M. UFFIC  
P. D. CHENDEMI  
W. B. KENNA  
F. J. LONG  
C. E. MURPHY  
J. T. SUTHERLAND  
K. M. CLARK

REPORT NUMBER RO-270/79-5

Lewis  
Jenkins  
Bradford

TIME/DATE OF INCIDENT 6/30/79 TIME/DATE OF DISCOVERY 1715 7/3/79

UNIT(S) 2 UNIT STATUS AT TIME OF INCIDENT 99% F.P.

DESCRIPTION OF INCIDENT: 5 of the 6 Condenser Cooling Water Emergency Discharge Valves were found to be locked closed. They should have been locked open. This was the result of either a personnel error or a procedural problem.

HOW INCIDENT WAS DISCOVERED: an operator was isolating the 2A2 Condenser waterbox with the intent of looking for a tube leak in the condenser

IMMEDIATE CORRECTIVE ACTION: 4 of the 5 valves were opened by 0830-6/30/79. One of the valves (2CCW-2) was left shut as the 2A2 waterbox was being isolated.

REPORTABLE PURSUANT TO TECHNICAL SPECIFICATION To be determined

DATE REPORT DUE TO NRC/OTR 7/17/79

TIME/DATE TELECOPIED OR OTHERWISE TRANSMITTED TO NRC/OTR 7/4/79 1030

PREPARED BY DJ Vito PHONE (803) 882-5363

7908020428

REGULATORY DOCKET FILE COPY

A002  
5/10