

Part 21 (PAR)

Event # 51988

Rep Org: CURTISS WRIGHT		Notification Date / Time: 06/08/2016 09:27 (EDT)	
Supplier: STRUTHERS-DUNN		Event Date / Time: 06/08/2016 (EDT)	
Last Modification: 06/08/2016			
Region: 3	Docket #:		
City: CINCINNATI	Agreement State:	Yes	
County:	License #:		
State: OH			
NRC Notified by: TIMOTHY FRANCHUK	Notifications: BILLY DICKSON	R3DO	
HQ Ops Officer: JEFF HERRERA	FRANK ARNER	R1DO	
Emergency Class: NON EMERGENCY	ANTHONY MASTERS	R2DO	
10 CFR Section:	JOHN KRAMER	R4DO	
21.21(a)(2) INTERIM EVAL OF DEVIATION	PART 21/50.55 REACTORS	EMAIL	

PART-21 REPORT - NONCONFORMANCE ON STRUTHERS-DUNN RELAY FOR PSEG NUCLEAR LLC

"This letter serves as an interim report in accordance with 10 CFR 21.21 pertaining to a potential deviation associated with Struthers-Dunn relays P/N B255XCXPFHSC125V supplied to PSEG Nuclear LLC. Based upon information obtained from PSEG, a defect may exist with the reset coil of the Struthers-Dunn relay listed above. Preliminary observations indicate the reset coil had shorted (opened) during operation, and that no other sub-components of the relay are believed to be associated with this failure. PSEG is aware of Curtiss-Wright's investigation into this failure.

"Evaluation of reportability in accordance with 10 CFR Part 21 is not able to be completed within the 60-day evaluation period due to the need for additional time to collect and evaluate the necessary information. It is currently expected that the evaluation of this defect will be completed by July 22, 2016."

POC: Timothy Franchuk
Director, Quality Assurance
4600 East Tech Drive
Cincinnati, Ohio 45245
(513) 528-7900

The licensee indicated that the current list of affected plants are being evaluated.

IE19
NRR

HOO Hoc

From: Hover, Margie <mhover@curtisswright.com>
Sent: Wednesday, June 08, 2016 12:08 PM
To: HOO Hoc
Cc: Franchuk, Timothy
Subject: [External_Sender] Interim 10 CFR Part 21 Report Regarding Disposition of a Non Conformance on Struthers-Dunn Relay
Attachments: QTNP3548 - U.S. Regulatory.Commission.pdf; Interim 10 CFR Part 21 Report (Struthers-Dunn Relay PN B255XCXPFHSC125V).pdf

Good afternoon:

I have attached a scanned copy of the above referenced documentation along with transmittal QTNP3548 being submitted by Timothy Franchuk.

Please confirm receipt by signing, dating and returning the Document Transmittal accompanying the attached documentation to Margie Hover, mhover@curtisswright.com.

Faxed copy receipt was confirmed by NRC via telephone conversation 6-8-2016.

Thanks and have a great day.

Margie Hover
Document Control Supervisor

Nuclear Division
Curtiss-Wright
4600 East Tech Drive, Cincinnati, OH, 45245, UNITED STATES
T: 513.201.2101
mhover@curtisswright.com | www.curtisswright.com/NuclearDivision

This e-mail and any files transmitted with it are proprietary and intended solely for the use of the individual or entity to whom they are addressed. If you have reason to believe that you have received this e-mail in error, please notify the sender and destroy this e-mail and any attached files. Please note that any views or opinions presented in this e-mail are solely those of the author and do not necessarily represent those of the Curtiss-Wright Corporation or any of its subsidiaries. Documents attached hereto may contain technology subject to government export regulations. Recipient is solely responsible for ensuring that any re-export, transfer or disclosure of this information is in accordance with applicable government export regulations. The recipient should check this e-mail and any attachments for the presence of viruses. Curtiss-Wright Corporation and its subsidiaries accept no liability for any damage caused by any virus transmitted by this e-mail.



4600 East Tech Drive
Cincinnati, Ohio 45245
(513) 528-7900

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

SUBJECT: INTERIM 10 CFR PART 21 REPORT REGARDING DISPOSITION OF A
NONCONFORMANCE ON STRUTHERS-DUNN RELAY PART NUMBER
B255XCXPFHSC125V FOR PSEG NUCLEAR LLC

This letter serves as an interim report in accordance with 10 CFR 21.21 pertaining to a potential deviation associated with Struthers-Dunn relays P/N B255XCXPFHSC125V supplied to PSEG Nuclear LLC. Based upon information obtained from PSEG, a defect may exist with the reset coil of the Struthers-Dunn relay listed above. Preliminary observations indicate the reset coil had shorted (opened) during operation, and that no other sub-components of the relay are believed to be associated with this failure. PSEG is aware of Curtiss-Wright's investigation into this failure.

Evaluation of reportability in accordance with 10 CFR Part 21 is not able to be completed within the 60-day evaluation period due to the need for additional time to collect and evaluate the necessary information. It is currently expected that the evaluation of this defect will be completed by July 22, 2016.

If you have any questions pertaining to this information, please contact Timothy Franchuk, Director of Quality Assurance, at 513-201-2176.

Sincerely,

Timothy Franchuk
Director, Quality Assurance
Nuclear Division
Curtiss-Wright

cc: Regional Administrator, USNRC, Region II

CURTISS - WRIGHT

Nuclear Division
4600 East Tech Drive, Cincinnati, OH 45245
T: 513.528.7900 | F: 513.528.4537

**DOCUMENT
TRANSMITTAL
QTNP3548**

CONTRACT
N/A

P.O. NUMBER
N/A

TO: NRC'S DOCUMENT CONTROL DESK
U.S. REGULATORY COMMISSION
WASHINGTON, DC 20555-0001

ATTN: HOO HOC
(301) 816-5151

PROJECT: _____

ACTION

LEGEND

STATUS

1. For Approval
2. Final Documents for Record
3. For Information Only
4. For Preliminary Use
5. For Your Use
6. Revised as Requested

- A. Approved-Released for Construction
- B. Approved as noted- Resubmit- Construction may proceed
- C. Not approved- Resubmit
- D. _____

DOCUMENT/ DRAWING NUMBER	REV.	NO. OF PRINTS/ COPIES	NO. OF SEPIAS	<input type="checkbox"/> DRAWINGS <input type="checkbox"/> SPECIFICATION <input type="checkbox"/> OTHER	<input checked="checked" type="checkbox"/> REPORTS <input type="checkbox"/> PROCEDURE	LEGEND
N/A	N/A	1				2
INTERIM 10 CFR PART 21 REPORT REGARDING DISPOSITION OF A NONCONFORMANCE ON STRUTHERS-DUNN RELAY PART NUMBER B255XCXPFHSC125V FOR PSEG NUCLEAR LLC						

REMARKS **PLEASE EMAIL MARGIE HOVER CONFIRMATION OF RECEIPT mhover@curtisswright.com. THANK YOU.**

BY Margie Hover DATE: 6/8/2016
DOCUMENT CONTROL

PAGE: 1 of 1

PLEASE ACKNOWLEDGE RECEIPT BELOW AND RETURN A SIGNED COPY

RECEIVED BY _____

DATED _____

In order to avoid delays in the project these documents must be returned by: _____