

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Industrial Maintenance Engineering, Inc., d/b/a Ais Gauging 5350 N. 13th Street Terre Haute, Indiana 47805 REPORT NUMBER(S) 2016001		2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S) 030-34598	4. LICENSE NUMBER(S) 13-32049-01	5. DATE(S) OF INSPECTION June 13 2016	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Luis Nieves Folch		4/13/2016
BRANCH CHIEF	Aaron T. McCraw		7/12/16

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Industrial Maintenance Engineering, Inc., d/b/a Ais Gauging 5350 N. 13th Street Terre Haute, Indiana 47805 REPORT NUMBER(S) 2016001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 030-34598	4. LICENSE NUMBER(S) 13-32049-01	5. DATE(S) OF INSPECTION June 13, 2016
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01-03.07
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03225	2. PRIORITY 5	3. LICENSEE CONTACT John B. Young - RSO	4. TELEPHONE NUMBER (812) 466-5478
---------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: June 13, 2021

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was a routine, unannounced inspection of a licensee that provides service. The licensee was authorized to perform shutter checks, leak testing, installation, removal, relocation, and calibration services for customers who possessed fixed gauges. The licensee activities were limited to 4 customers within NRC jurisdiction, these activities occurred proximately 2 times a year and the sources they service are authorized general license. The licensee sends leak test samples to another service company for evaluation. The licensee possessed Krypton-85 and Strontium-90 for the development of their own gauges.

Performance Observations

No licensed activities were performed at the time of inspection within NRC jurisdictions; therefore a temporary job site was not inspected. Licensee personnel described procedures for performing leak tests, shutter checks, radiation surveys, and installation and relocation services. Interviews with licensee staff indicated sufficient knowledge of radiation safety principals. The inspector reviewed annual audits, dosimetry reports, survey of sources in storage, and hazmat training.

No violations of NRC requirements were identified as a result of this inspection.

Note to the inspector:

In order to inspect at a temporary job site, the inspector should announce the inspection and schedule it for a period and a location when within NRC jurisdiction.

*WSP
for
ATM
7/14/16*