

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Regional Cardiology Ass. PLLC
3399 Pallock Rd
GRAND ~~BLANC~~ Blanc, MI 48439

REPORT NUMBER(S) 2016001

2. NRC/REGIONAL OFFICE
 Region III
 U. S. Nuclear Regulatory Commission
 2443 Warrenville Road, Suite 210
 Lisle, IL 60532-4352

3. DOCKET NUMBER(S)
 030- 35626

4. LICENSE NUMBER(S)
 21-32298-01

5. DATE(S) OF INSPECTION
 7/13/16

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
 (Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	E.L. Kulzer	<i>E.L. Kulzer</i>	7/13/16
BRANCH CHIEF	AT McCraw	<i>DAR... for AT McCraw</i>	8/5/16

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Regional Cardiology Associates, P.L.C. 3399 Pallock Rd Grand Blanc, MI. 48439 REPORT NUMBER(S) 2015001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 030-35626	4. LICENSE NUMBER(S) 21-32298-01	5. DATE(S) OF INSPECTION 7/13/16
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED IP 87130	7. INSPECTION FOCUS AREAS 03.01 through 03.07
---	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT James Kure	4. TELEPHONE NUMBER (248) 933-8030
---------------------------------	----------------------	---------------------------------------	---

Main Office Inspection Next Inspection Date: 7/13/2021

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was a routine unannounced inspection of a private practice cardiology clinic authorized to use licensed material permitted 10 CFR 35.100, and 35.200. Nuclear cardiology studies were performed on Mondays, Tuesdays, Thursdays, and Fridays. The clinic employed two technologists who perform 45 patient studies each week. The licensee obtained unit doses from a local radiopharmacy.

The inspection consisted of interviews with licensee personnel, a review of selected records, a tour of the nuclear medicine department, and independent measurements. The inspection included observations of a dose calibrator QA check, security of licensed material, use of personnel monitoring, packaging receipt, waste disposal records, quarterly audits, training records, and surveys. Dosimetry records indicated maximum whole body and extremity readings for 2016 of 213 millirem (mrem) and 610 mrem respectively. The inspector observed the licensee personnel prepare and administer unit doses for cardiac rest and stress testing procedures.

No violations of NRC regulatory requirements were identified during this inspection.

Handwritten signature and date:
ATM
8/5/2016