



**KHNP**

**KOREA HYDRO & NUCLEAR POWER CO., LTD**

70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA

Tel: +82-42-870-5740 / Fax: +82-42-870-5779

<http://www.khnp.co.kr>

August 16, 2016  
Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

Attention: Mr. Jeff Ciocco  
Division of New Reactor Licensing

Docket No. 52-046  
MKD/NW-16-0885L

**Subject: Supplemental Response to RAI 334-8373 for the Question 03.12-17**

**References: 1) NRC Request for Additional Information 334-8373, dated December 14, 2015**  
**2) KHNP Letter MKD/NW-16-0150L, Response to RAI 334-8373 for Question 03.12-17, dated February 24, 2016**

KHNP is hereby submitting a supplemental response to RAI 334-8373, dated December 14, 2015. The supplemental RAI response to Question 03.12-17 explains specifying gaps for frame type supports on design drawings for the large diameter and high temperature piping in the RCB.

The enclosure provides the supplemental response to RAI 334-8373 for the Question 03.12-17 (Non-Proprietary).

If additional information or clarification is required, please contact Daegeun Ahn, Director of KHNP Washington DC Center at [ahn.daegeun@khnp.co.kr](mailto:ahn.daegeun@khnp.co.kr) or 703-388-0592.

Sincerely,

---

Jae-yong Lee  
Project Manager  
Advanced Reactors Development Laboratory  
Korea Hydro and Nuclear Power Co., Ltd

Enclosure: Supplemental Response to RAI 334-8373 for the Question 03.12-17 (Non-Proprietary)

## **Enclosure**

Supplemental Response to RAI 334-8373 for the Question 03.12-17

(Non-Proprietary)

August 16, 2016