

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Eye Lighting International of North America, Inc. 9150 Hendricks Road Mentor, Ohio 44060 REPORT NUMBER(S) 2016001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-35694	4. LICENSE NUMBER(S) 34-23877-01E	5. DATE(S) OF INSPECTION August 1, 2016
--------------------------------------	--	--

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
 (Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Geoffrey M. Warren	<i>Gj V</i>	8/1/16
BRANCH CHIEF	Aaron T. McCraw	<i>Robert D. Gattuso, Jr. for ATM</i>	8/16/16

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Eye Lighting International of North America, Inc. 9150 Hendricks Road Mentor, Ohio 44060 REPORT NUMBER(S) 2016001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-35694	4. LICENSE NUMBER(S) 34-23877-01E	5. DATE(S) OF INSPECTION August 1, 2016
--------------------------------------	--	--

6. INSPECTION PROCEDURES USED 87125	7. INSPECTION FOCUS AREAS 03.01, 03.03, 03.06 - 03.07, as relevant to program
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03251	2. PRIORITY 5	3. LICENSEE CONTACT John Hecht, RSO	4. TELEPHONE NUMBER (216) 591-0302
---------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: August 1, 2021

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was a routine, unannounced, inspection. The licensee distributed metal halide lamps (light bulbs) containing krypton-85 (Kr-85) as exempt materials. The lamps were either received already packaged from the manufacturer in Japan or assembled and packaged on site from materials including Kr-85 tubes imported from Japan. No unsealed materials were possessed on site. This NRC license authorized only the exempt distribution of the finished lamps; materials were possessed and prepared at this site under a specific manufacturing and distribution license issued by the State of Ohio. The licensee distributed Kr-85 lamps only within the United States. The licensee had provided to the NRC annual reports of materials distributed under the license each January since the previous inspection as required by 10 CFR 32.16(a).

Performance Observations: The inspector observed that a selection of bulbs containing Kr-85 were all labeled as such. The licensee demonstrated how the bulbs were tracked and shipped, and described reminders to provide the required annual reports. Interviews with licensee staff indicated sufficient knowledge of radiation safety concepts and procedures.

No violations of NRC requirements were identified.

BB - for ATM