

NRC INSPECTION MANUAL

DIRS

Change Notice 16-021

DELETED:		TRANSMITTED:	
<u>Number</u>	<u>Date</u>	<u>Number</u>	<u>Date</u>
1. IP 95001	02/09/11	IP 95001	08/24/16
2.			

TRAINING: No

REMARKS: IP 95001, "Supplemental Inspection Response to Action Matrix Column 2 Inputs," has been revised to incorporate Staff Requirements Memorandum, SECY-15-0108 "Recommendation to Revise the Definition of Degraded Cornerstone as used in the Reactor Oversight Process" direction to revise IP 95001 to include additional resources [Increased from "approximately 40 hours" to "approximately 40 hours to complete for one white issue and approximately 120 hours to complete for two white issues"] and guidance to be used to review licensee common cause analyses when a licensee has a second White input in the same cornerstone in order to consider the potential for programmatic weaknesses in a licensee's performance. [C2]

Also simplified the IP title; formatted to support navigation pane; incorporated language consistent with 10 CFR 50 Appendix B Criterion XVI (e.g. "prompt" vs. "timely" and "preclude repetition" vs. "prevent recurrence"); addressed ROP Feedback Form 95001-1797 and partially addressed ROPFF 95001-2009; updated safety culture terminology to conform to IMC 0310 revision per ROPFF 95002-2144.

DISTRIBUTION:

- Standard
 Official Use Only (OUO)-Security Related Information.

Please contact: _____ Phone: _____

END