

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

*Central File*  
*50-369*  
*510*  
*387*

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

August 3, 1978

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: RII:JPO  
50-269  
50-270  
50-287

Dear Mr. O'Reilly:

Your letter of June 27, 1978 transmitted OIE Bulletin 78-10 concerning Bergen-Paterson hydraulic shock suppressor accumulator spring coils. In this regard a review has been conducted at Oconee Nuclear Station and it has been determined that no Bergen-Paterson hydraulic suppressors are in use, in spares or planned for future use.

Very truly yours,

*William O. Parker, Jr.*  
William O. Parker, Jr.

RLG:scs

cc: Director, NRC Office of Inspection and Enforcement  
Division of Reactor Operations Inspector

*A0/2*

*R*