

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Valley Inspection Service, Inc. 430 Business Park Lane Allentown, Pennsylvania 18109 REPORT NUMBER(S) 2016-001 & 2016-002	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713
--	--

3. DOCKET NUMBER(S) 030-31172	4. LICENSE NUMBER(S) 37-28385-01	5. DATE(S) OF INSPECTION July 26, August 4 & September 1, 2016
----------------------------------	-------------------------------------	---

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)




10 CFR 34.43(e)(1) requires, in part, that the RSO or designee conduct an inspection program of the job performance of each radiographer and radiographer's assistant to ensure that the Commission's regulations, license requirements, and the licensee's operating and emergency procedures are being followed. The inspection program must include observation of the performance of each radiographer and radiographer's assistant during an actual industrial radiographic operation at intervals not to exceed 6 months.

Contrary to the above, the RSO or designee did not conduct an inspection of the job performance of a radiographer's assistant during an actual industrial radiographic operation at an interval of 6 months or less. Specifically, on October 21, 2015, a radiographer's assistant performed radiographic operations in Wilmington DE and their last inspection of job performance was on February, 9, 2015, during the individual's practical exam, an interval exceeding 6 months. (Severity Level IV)

The licensee's corrective actions are to include the radiographer's assistant to the spreadsheet for tracking six month performance assessments.

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Robert Kratzer, President/RSO		9/1/16
NRC INSPECTOR	John Miller		9/1/16
BRANCH CHIEF	Blake Welling		9/2/16

SUNSI Review Completed By: _____ John Miller

Public Non-Sensitive