

THE CHURCH OF
JESUS CHRIST
OF LATTER-DAY SAINTS

SPRINGFIELD MO FM GROUP
1357 South Ingram Mill Road
Springfield, Missouri 65804-0625
Phone: 1-417-889-4136
Facsimile: 1-417-889-2125

August 17, 2016

Director of FSME
Attn: GLTS
USNRC
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on 8/17/2016 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2015. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Arlaine R. Bell 417-889-4136.

Sincerely,

Arlaine R. Bell

Encl.

SERIAL NUMBER SPREADSHEET

Company Name	Springfield MO FM Group	Date	8/10/2016
Address 1	1357 S. Ingram Mill Rd	Isolite RMA #	FMACQ 187585
Address 2		EWS Order #	FMACQ 187612
Address 3		MTS Order #s	
City/State	Springfield MO	Contact Name	Arline RBell
Zip/Post Code	65804	Contact Phone	417-889-4136
Country	USA	Contact FAX	---
		Contact E-mail	arline.bell@ldschuch.org

#1

Area
#



#2

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	Shield	SLX-60	11-44214	---	---	0.370
2	Shield	SLX-60	11-44217	---	---	0.370
3	Shield	SLX-60	11-44216	---	---	0.370
4	Safety	---	192006	9	96	10
5	Shield	SLX-60	11-44216	---	---	0.370
6	Safety	---	192005	9	96	10
7	Safety	---	191990	9	96	10
8	Safety	---	192004	9	96	10
9	Safety	---	192003	9	96	10
10	Safety	---	192007	9	96	10
11	Perm EX	P-160	107075	1	96	25ci
12	Perm EX	P-160	107073	1	96	25ci
13	Perm EX	P-160	107070	1	96	25ci
14	Perm EX	P-160	107076	1	96	25ci
15	Perm EX	P-16	107071	1	96	25ci

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs--not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	Springfield MO PMG	Date	8/10/2016
Address 1	13515 Ingram Mill Rd	White RMA #	PMAC 0187585
Address 2		EWS Order #	PMAC 0187587
Address 3		MTS Order #s	
City/State	Springfield MO	Contact Name	Arline Bell
Zip/Post Code	65804	Contact Phone	417-8874136
Country	USA	Contact FAX	
		Contact E-mail	arlinebell@ldschurch.org

#3

—

#4

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	PermEx	T-4001	107668	1	96	25ci
2	Shield	201	K5039	7	96	11.5
3	Shield	201	K5038	7	96	11.5
4	Shield	201	K5033	7	96	11.5
5	Shield	201	K5022	7	96	11.5
6	PermEx	T-4001	107063	1	96	25cc
7	PermEx	T-4001	107064	1	96	25ci
8	Safety	—	191994	—	—	25ci
9	Safety	—	191995	1	96	0.37
10	Safety	—	192001	1	96	0.37
11	Safety	—	192000	1	96	0.37
12	Safety	—	191999	1	96	0.37
13	Safety	—	191991	1	96	0.37
14	PermEx	T4001	107074	1	96	25
15						

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs---not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	Springfield	Date	8/10/2016
Address 1	1359 So. Ingram Rd	Isolite RMA #	FMACO 187588
Address 2		EWS Order #	FMACO 1875112
Address 3		MTS Order #s	
City/State	Springfield MO	Contact Name	Arlain R Bell
Zip/Post Code	65804	Contact Phone	417-889-436
Country	USA	Contact FAX	
		Contact E-mail	arlain.bell@ldschurch.org

#5

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "C" or "TBq"
				Month	Year	
1	Perm EX	T-4001	107065	1	96	25 CI
2	Perm EX	T-4001	107069	1	96	25 CI
3	Perm EX	T-4001	107062	1	96	25 CI
4	Shield	SCX60	1145288	1	96	0.370
5	Shield	SCX60	1145299	1	96	0.370
6	Safety	SCX60	65074	1	96	20
7	Perm EX	T-4001	107067	1	96	20
8						
9						
10						
11						
12						
13						
14						
15						

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs--not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.



DOT Hazmat Training and Acknowledgement FOR RETURN OF SELF-LUMINOUS EXIT SIGNS

- Self-Luminous EXIT signs are illuminated with internal light sources powered by tritium gas. Tritium gas is a radioactive isotope of hydrogen. For this reason, Federal Regulations require that any person shipping this product must have training sufficient to comply with US Department of Transportation regulations in the Code of Federal Regulations #49 Part 172.
- To receive this training, the shipper must read, understand and perform the following steps. Place a check mark at each step after complete. Sign and date this form. Upon receipt of this completed form we will provide you with the RMA Number required for the return of these signs along with complete shipping instructions.
- Keep this completed form in your files for at least 3 years in case of regulatory inspection.

- The EXIT signs are to be shipped as excepted packages for radioactive instruments and articles (49CFR 173.424). No special packaging is necessary.
- A sturdy cardboard box, plastic drum, or metal drum will be sufficient to ship the signs because they all meet the general package design requirements of 49CFR 173.410. The package must withstand normal conditions of transport without any deterioration. The container must be clean and never have been near other radioactive material so that the shipper can be sure that there is no radioactive contamination on the outside of the container.
- You must ensure that the active materials (the glowing inner tubes) are completely enclosed by non-active components (the plastic sign housing). Therefore, each sign must be visually inspected to ensure that it is not crushed or punctured in a way that might cause an inner light tube to be broken.
- Each sign must contain less than 20 curies of tritium (see the sign's rear label). The total amount of curies to be placed into each container must be less than 100 Ci. (Add up the curie content of each sign as you put them into the container.)
- If a transportation incident occurs, you must report the incident to the USDOT per 49 CFR 171.15 and 171.16.
- Read and understand the "Packaging Instructions" and follow each step exactly.

FMALQ 187610 187611
MTS Order Number

FMA6Q 187583 187584
EWS Purchase Order Number

Arlaire RBell
Name (Printed)

The Church of Jesus Christ of LDS
Company

Arlaire RBell
Signature

6/28/2014
Date

If you have any questions, call Isolite at 800-888-5483.