

*Central File*  
50-269  
370  
287

DUKE POWER COMPANY

USNRC REGION II POWER BUILDING  
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

NOV 14 10 49 AM '79  
November 9, 1979

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303


Re: RII:JPO  
50-269  
50-270  
50-287

Dear Mr. O'Reilly:

With regard to my letter of August 24, 1979, please find attached a response to Item 5 of IE Bulletin 79-05c. This response includes the Small Break Operating Guidelines for Oconee as well as "Analysis Summary in Support of Inadequate Core Cooling Guidelines for a Loss of RCS Inventory."

Procedures will be developed and operators will be trained on the procedures related to inadequate core cooling. It is expected that this will be completed by January 15, 1980.

Very truly yours,

  
William O. Parker, Jr.

RLG:scs  
Attachment

cc: Director, Office of Inspection & Enforcement  
Washington, D. C. 20555

Director, Office of Nuclear Reactor Regulation  
Washington, D. C. 20555

790649  
7912060 549