

*Central File*

*50-269  
270  
287*

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

JUN 13 4 15: 17

June 13, 1980

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287

Dear Mr. O'Reilly:

Your letter of March 13, 1980 transmitted Bulletin 80-06, which requires a detailed review of Engineered Safeguards (ES) components to assure that they remain in their safety modes following reset of the ES signal. That review has not been completed. A response to the items contained in the bulletin will be provided by July 14, 1980.

Very truly yours,

*William O. Parker, Jr.*  
William O. Parker, Jr. *By [Signature]*

SRL:scs

*[Handwritten mark]*

*[Handwritten mark]*

8006300 213

OFFICIAL COPY