

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083

August 5, 1980

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: Oconee Unit 1
Docket No. 50-269

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-269/80-23. This report is submitted pursuant to Oconee Nuclear Station Technical Specification 6.6.2.1.a(4), which concerns a reactivity anomaly of greater than 1.0% $\Delta k/k$, and describes an incident which occurred while Oconee 1 was starting up and which is considered to be of no significance with respect to the health and safety of the public.

My letter of July 23, 1980 addressed the delay in the preparation of this report.

Very truly yours,



William O. Parker, Jr.

FTP:vr
Attachment

cc: Director
Office of Management & Program Analysis
USNRC
Washington, D. C. 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
P. O. Box 10412
Palo Alto, California 94303

A002
S
1/1

8008110 4/10 S