NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201 U.S. NUCLEAR REGULATORY C					
SAFI	TY INS	PECTION REPORT	AND COMPLIANCE II		
1. LICENSEE/LOCATION INSPECTED: Molecular Imaging Services, Inc. d/b/a Cardiology PC Farmington, Connecticut REPORT NUMBER(S) 2016-001			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
3. DOCKET NUMBER(S) 4. LICENSE NUMBER(SI	5. DATE(S) OF INSPECTI	ON	
030-36176		07-30790-01		7/26/2016, exit on 10/13/2016	
LICENSEE:					
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
Statement of Corrective Actions I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.					
Title		Printed Name		Signature	Date
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Héctor	Bermúdez	facts	he Bernet	10/13/2016
BRANCH CHIEF	James	Dwyer		3	16/19/14
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013) G:\WordDocs\Current\Insp Record\R07-30790-01.2016001.591M-Part1.doc					
SUNSI Review Completed By:	/RA	/ HBermúdez		X Public X	Non-Sensitive