

DUKE POWER COMPANY  
POWER BUILDING  
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

March 4, 1981

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: Oconee Nuclear Station  
Docket No. 50-287

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-287/81-2. This report is submitted pursuant to Oconee Nuclear Station Technical Specification 6.6.2.1.a(3), which concerns abnormal degradation of the RC Pressure Boundary, and describes an incident which is considered to be of no significance with respect to its effect on the health and safety of the public.

A preliminary letter report concerning this incident was submitted to your office on February 18, 1981.

Very truly yours,

*William O. Parker, Jr. by WAH*  
William O. Parker, Jr.

JLJ:pw  
Attachment

cc: Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Bill Lavalley  
Nuclear Safety Analysis Center  
P. O. Box 10412  
Palo Alto, California 94303

5

8103110491

A002  
5/11