

THE CHURCH OF
JESUS CHRIST

OF LATTER-DAY SAINTS

SUMMIT COUNTY UT FM GROUP

P.O. Box 60
Oakley, Utah 84055-0060
Phone: 435-783-5799
Facsimile: 435-783-5798

September 29, 2016

Director of FSME

Attn: GLTS

USNRC

Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on 9/29/16 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2015.

As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact:

Catherine Kennington 435-640-4144

Sincerely,



Catherine Kennington

Encl.

SERIAL NUMBER SPREADSHEET

Company Name	Summit County UT FMG	Date	9/27/16
Address 1	1224 W State Road 32	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	
City/State	Oakley, Utah	Contact Name	Catherine Kennington
Zip/Post Code	84055	Contact Phone	435-640-4144
Country	USA	Contact FAX	
		Contact E-mail	cathy.kennington@ldschurch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	SRB Technology	B100	585736	1	1995	20 Curies
2	SRB Technology	B100	missing	missing	missing	20 Curies
3	SRB Technology	B100	missing	missing	missing	20 Curies
4	SRB Technology	B100	585742	1	1995	20 Curies
5	SRB Technology	B100	missing	missing	missing	20 Curies
6	SRB Technology	B100	missing	missing	missing	20 Curies
7	SRB Technology	B100	585738	1	1995	20 Curies
8	SRB Technology	B100	585740	1	1995	20 Curies
9	SRB Technology	B100	585737	1	1995	20 Curies
10	SRB Technology	B100	585743	1	1995	20 Curies
11	SRB Technology	B100	missing	missing	missing	20 Curies
12	SRB Technology	B100	585767	illegible	illegible	20 Curies
13	SRB Technology	B100	missing	missing	missing	20 Curies
14	SRB Technology	B100	missing	missing	missing	20 Curies
15	SRB Technology	B100	missing	missing	missing	20 Curies

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs---not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	Summit County UT FMG	Date	9/27/16
Address 1	1224 W State Road 32	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	
City/State	Oakley, Utah	Contact Name	Catherine Kennington
Zip/Post Code	84055	Contact Phone	435-640-4144
Country	USA	Contact FAX	
		Contact E-mail	cathy.kennington@ldschurch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	SRB Technology	B100	missing	missing	missing	20 Curies
2	SRB Technology	B100	585732	1	1995	20 Curies
3	SRB Technology	B100	missing	missing	missing	20 Curies
4	SRB Technology	B100	585730	1	1995	20 Curies
5	SRB Technology	B100	missing	missing	missing	20 Curies
6	SRB Technology	B100	572263	3	1994	20 Curies
7	SRB Technology	B100	572314	3	1994	20 Curies
8						
9						
10						
11						
12						
13						
14						
15						

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs---not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.